

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

AUG 29 2013

Form C-141
Revised October 10, 2003

Submit to the appropriate District Office in accordance with 19.15.29 NMAC

Release Notification and Corrective Action

NJM 1324155325

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating	Contact: Joe Hernandez
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: Turner B 93	Facility Type: Oil Producer
Surface Owner: Federal	Mineral Owner: Federal
API No.: 3001526611	

LOCATION OF RELEASE



Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	20	17S	31E	1140	South	2560	West	Eddy

Latitude: 32.8159378158125 Longitude: -103.892121078496

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 4 bbls	Volume Recovered: 0
Source of Release: Stuffing box	Date and Hour of Occurrence: 12/3/2012 1:30pm	Date and Hour of Discovery: 12/3/2012 2pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Terry Gregston- BLM	
By Whom? Joe Hernandez	Date and Hour 12/4/2012 3pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*:		
Describe Cause of Problem and Remedial Action Taken.*: SUPERVISOR RECEIVED A CALL FROM CHEMICAL GUY AND GAVE ME A CALL TO VERIFY IF WELL WAS LEAKING, DROVE TO LOCATION AND NOTICE WATER ON GROUND COMING OUT OF WELL PACKING TURN WELL OFF AND PACK WELL. TURNED WELL ON.		
Describe Area Affected and Cleanup Action Taken.* : From well head fluid ran N20' then SW 70' to sw corner of loc. spill was 2'x70' PICKED UP CONTAMINATED DIRT AND PUT IT ON PILE ON SIDE OF LOCATION.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Joe Hernandez	Approved by District Supervisor Signed By 	
Title: Production Foreman	Approval Date: AUG 29 2013	Expiration Date:
E-mail Address: jhernandez@linenergy.com	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	Attached <input type="checkbox"/>
Date: 12/10/2012 Phone: 575-942-9492		

* Attach Additional Sheets If Necessary

SEPTEMBER 29, 2013

2RP-1878