District I 1625 N. French Dr., Hobbs, NM 88240 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

State of New Mexico Energy Minerals and Natural Resources AUG 28 2013

Form C-141 Revised October 10, 2003

1220 South St. Francis Dr. Santa Fe. NM 87505

Oil Conservation Division NMOCE LANTE Mappropriate District Office in accordance with 19.15.29 NMAC

1220 S. St. Francis Dr., Santa Fe, NM 87505 **Release Notification and Corrective Action** 24937466 **OPERATOR** ☐ Initial Report Final Report 69324 Contact: Brian Wall Name of Company: Linn Operating Telephone No.: 575-738-1739 Address: 2130 W. Bender Hobbs, NM 88240 Facility Name: Turner B North Battery - Turner B 95 Facility Type: Battery API No.: 3001526612 Surface Owner: Federal Mineral Owner: LOCATION OF RELEASE Unit Letter Township Feet from the North/South Line Feet from the East/West Line Section Range County 20 17S 31E 2610 South 1000 West Eddy L Latitude: 32.8199711236509 Longitude: -103.897239412252 NATURE OF RELEASE Type of Release: Oil / Produced Water Volume of Release: 85bbls/ 5bbls Volume Recovered: 70bbls/ 0bbl Source of Release: Battery Date and Hour of Occurrence: Date and Hour of Discovery: 08/27/2013 8:00am 08/27/2013 8:00am Was Immediate Notice Given? If YES, To Whom? Mike Burton- BLM Mike Bratcher- NM OCD By Whom? Brian Wall Date and Hour 08/27/2013 08/28/2013 Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ☐ Yes ☒ No If a Watercourse was Impacted, Describe Fully.*: Describe Cause of Problem and Remedial Action Taken. *: 8-27-13 Pulled up to battery seen oil tank #3 leaking from the bottom called vac truck to pick up stand fluid. Describe Area Affected and Cleanup Action Taken.*: Affected area approx 15'X20'. Had vaccum truck pick up oil and clean up spill.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other

E-mail Address: bwall@linnenergy.com Phone: 806-367-0645 Date: 08/28/2013 Attach Additional Sheets If Necessary

federal, state, or local laws and/or regulations.

Signature:

Printed Name: Brian Wall

Title: Construction Foreman II

Remediation per OCD Rule & Guidelines, & like approval by BLM. <u>SUBMIT REMEDIATION</u> PROPOSAL NO LATER THAN:

Approved by District Supervisorioned Ry

Approval SEP 0 6 2013

Conditions of Approval:

OIL CONSERVATION DIVISION

Expiration Date:

Attached

tober 6,2013


Bratcher, Mike, EMNRD

From: McCracken, Theresa <TMcCracken@linnenergy.com>

Sent: Wednesday, August 28, 2013 8:54 AM **To:** Bratcher, Mike, EMNRD; mburton@blm.gov

Cc: Callahan, Terry; Moreno, Laura; Butters, Thomas; Golding, Chris; Wall, Fred

Subject: Linn- Turner B North Battery 8-27-13 **Attachments:** Turner B North Battery 8-27-13.pdf



Please find attached the initial C-141 for the above referenced location.

Thank you,



Theresa McCracken

Field Administrator

LINN Energy, LLC
2130 W Bender

Hobbs, NM 88240

T: 575-738-1739 / F: 575-738-1740

tmccracken@linnenergy.com

This electronic message, together with any attachments, contains information from LINN Energy that may be confidential and intended solely for the use of the addressee only. If you are not the intended recipient, please note that any disclosure, dissemination, distribution or copying of this message, or any attachment, is strictly prohibited. Also, please notify the original sender by return e-mail and delete the message, along with any attachments, from your computer. Finally, the recipient should check this email and any attachments for the presence of viruses. The organization accepts no liability for any damage caused by any virus transmitted by this email.