

RECEIVED

1/2

OCT 04 2012

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
2040 South Pacheco
Santa Fe, NM 87505

NMOCD ARTESIA

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

JMW 1326840258 23435 OPERATOR ☐ Initial Report ☒ Final Report

Name of Company	TRANSWESTERN PIPELINE CO.	Contact	LARRY CAMPBELL
Address	6381 NORTH MAIN ST ROSWELL, NM	Telephone No.	(575) 625-8022
Facility Name	VALVE 109	Facility Type	VALVE SITE
Surface Owner	Mineral Owner	Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	29	16S	22E					CHAVES

Latitude: 32.907702 Longitude: 104.070624

NATURE OF RELEASE

Type of Release	NATURAL GAS	Volume of Release	21,031.567 mcf	Volume Recovered	<input checked="" type="checkbox"/>
Source of Release	PIPELINE DEPRESSURIZATION	Date and Hour of Occurrence	10/3/12	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	OCD ARTESIA		
By Whom?	L. Campbell	Date and Hour	03:15 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.* DUE TO A PIPELINE MAINTENANCE ACTIVITY TO REPLACE A VALVE, THE NATURAL GAS IN THE PIPELINE HAD TO BE RELEASED TO COMPLETE THE VALVE REPLACEMENT

Describe Area Affected and Cleanup Action Taken.* N/A

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Larry Campbell</i>	OIL CONSERVATION DIVISION	
Printed Name: LARRY CAMPBELL	Approved by <input checked="" type="checkbox"/> District Supervisor	Accepted for record NMOCD
Title: Sr. ENVIRONMENTAL SPECIALIST	Approval Date: SEP 25 2013	Expiration Date:
Date: 10/4/2012 Phone: (575) 625-8022	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

JMW 1326840026

JMW 1326840681

2RP-1933