

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

MAY 17 2013

NMOCD ARTESIA

Form C-141  
Revised March 17, 1999  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

nJMW 1326849581 OPERATOR ☒ Initial Report ☒ Final Report

Name of Company- Transwestern Pipeline Co. 23435	Contact <input type="checkbox"/> Randy Smith	
Address Bounds Rd	Telephone No. <input type="checkbox"/> 505-885-8525	
Facility Name Crawford Station	Facility Type <input type="checkbox"/> Nat. Gas Compression	
Surface Owner Transwestern Pipeline	Mineral Owner	Lease No. <input type="checkbox"/>

LOCATION OF RELEASE

32.263025 104.147928

Unit Letter	Section 36	Township T23S	Range R27E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy <input type="checkbox"/>
-------------	------------	---------------	------------	---------------	------------------	---------------	----------------	--------------------------------------

NATURE OF RELEASE

Type of Release Natural Gas	Volume of Release 9-MCF	Volume Recovered <input type="checkbox"/> 0
Source of Release Pipeline Compressor Blowdown	Date and Hour of Occurrence 5-16-2013 10:30 am started blowdown	
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? <input type="checkbox"/>	Date and Hour <input type="checkbox"/>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* None		
Describe Cause of Problem and Remedial Action Taken.* Pipeline Leak, blowdown and repair bad piping		
Describe Area Affected and Cleanup Action Taken.* None		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: Randy Smith	OIL CONSERVATION DIVISION	
Printed Name: Randy Smith	Approved by <input type="checkbox"/> District Supervisor: Accepted for record NMOCD	
Title: O+ M Tech	Approval Date: SEP 25 2013	Expiration Date:

fJMW 1326847894  
iJMW 1326850054

2RP-  
1935

**Bratcher, Mike, EMNRD**

---

**From:** Smith, Randy <Randy.Smith@energytransfer.com>  
**Sent:** Friday, May 17, 2013 10:53 AM  
**To:** Bratcher, Mike, EMNRD  
**Subject:** Gas release  
**Attachments:** DOCOCD CRAWFORD GAS RELEASE.PDF

Randy Smith, Mechanic  
Transwestern Pipeline Co.

Office: 575-885-8525  
Cell: 575-361-1512  
Fax: 575-885-1762

Mail: PO Box TT, Carlsbad NM 88221  
UPS/FEDEX: HWY 62-180 MM 63, Carlsbad NM 88220

Private and confidential as detailed [here](#). If you cannot access hyperlink, please e-mail sender.