

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

RECEIVED OCD

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company OXY USA WTP LP 16696	Contact Bernal, Thomas
Address 329 Marathon Rd, Lakewood	Telephone No. (575) 628-4112
Facility Name INDIAN BASIN GAS PLANT	Facility Type GAS PROCESSING PLANT

Surface Owner	Mineral Owner INDIAN BASIN	Lease No.
---------------	----------------------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------	---------	----------	-------	---------------	------------------	---------------	----------------	----------------

Latitude 32°27'52.502" Longitude 104°34'28.004"

NATURE OF RELEASE

Type of Release Gas	Volume of Release 81.3 MCF	Volume Recovered 0
Source of Release Acid Gas Flare - SSM	Date and Hour of Occurrence 9/7/2011 8:45:00 AM	Date and Hour of Discovery 9/7/2011 8:45:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

RECEIVED

OCT 03 2011

NMOCD ARTESIA

Describe Cause of Problem and Remedial Action Taken.\*

Cause:

SHUT ACID GAS COMPRESSOR DOWN FOR QUARTERLY OIL CHANGE. ALSO REPLACED 5TH STAGE SUCTION TRANSMITTER AND ADDED A REDUNDANT TRANSMITTER TO THE 1ST STAGE SUCTION.

Remedial Action Taken:

HAD EQUIPMENT STAGED AND EMPLOYEES IN POSITION TO CARRY OUT PREVENTATIVE MAINTENANCE TASKS IN A TIMELY MATTER.

Describe Area Affected and Cleanup Action Taken.\*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: Sandy Ballard

Printed Name: SANDY D BALLARD

Title: HES SPECIALIST

E-mail Address: Sandy\_ballard@oxy.com

Date: 9-15-2011

Phone: 575 6284122

Approved by District Supervisor:

Accepted for record  
NMOCD

SEP 30 2013

Approval Date:

Expiration Date:

Conditions of Approval:

Attached ☐

\* Attach Additional Sheets If Necessary

FJMW1327034125

FJMW1327338680

2RP-1953