

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW 1328038365

Name of Company Devon Energy		6137	Contact Tracy Kidd
Address P.O. Box 250, Artesia, NM 88211			Telephone No. 575-513-0628
Facility Name Snapping 10 Federal 1H			Facility Type Oil Well
Surface Owner		Mineral Owner	API No. 30-015-37899

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	10	26S	31E	330	NORTH	1980	EAST	EDDY

Latitude 32.0639223225352 Longitude -103.763906284766

NATURE OF RELEASE

Type of Release Spill	Volume of Release 10 bbls	Volume Recovered 0
Source of Release Poly line leak	Date and Hour of Occurrence 9-29-13 10:29 AM	Date and Hour of Discovery 9-29-13 3:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeffery Robins/BLM, Mike Bratcher/OCD	
By Whom? Aaron Kidd, Assistant Foreman	Date and Hour 10/01/2013, BLM 8:30am, OCD 8:45am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

(spoke w/ Gracie via phone on 10/4/13 to get a corrected date for the release, Jean Marie Warren)

RECEIVED

OCT 04 2013

NMOCD ARTESIA

Describe Cause of Problem and Remedial Action Taken.*

At the Snapping 10-3, a poly line leaked 10 bbls of oil through a pin size hole.

Describe Area Affected and Cleanup Action Taken.*

At the Snapping 10-3, a poly line leaked 10 barrels of oil through a pin size hole. The well tester turned production into the frac tank at 8:30 P.M on 9/28/13. and at 3:00 A.M on 9/29/13 he realized the poly fill line had been leaking beside the frac tank. It was a small pin hole in the poly line, over the period of 6.5 hours it leaked approximately 10 bbls of oil. The poly line was cut and replaced and put back into production and no fluid was recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Graciela C. Bustamante		OIL CONSERVATION DIVISION	
Printed Name: Graciela C. Bustamante		Approved by Environmental Specialist Signed By <i>Mike Bratcher</i>	
Title: Field Admin. Tech		Approval Date: OCT 07 2013	Expiration Date:
E-mail Address: Gracie.Bustamante@dvn.com		Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	Attached <input type="checkbox"/>
Date: 10/02/2013 Phone: 575-746-5561			

* Attach Additional Sheets If Necessary

NOVEMBER 7, 2013

2RP-1975