

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**nJMW1329548058** OPERATOR  Initial Report  Final Report

Name of Company <i>Enterprise Field Services LLC 100347</i>	Contact <i>Jim Heap</i>
<i>PO Box 4324, Houston, TX 77252</i>	Telephone No. <i>432-686-5404</i>
Facility Name <i>Pipeline ROW, Pennzoll 9 A-6 Lateral</i>	Facility Type: <i>Gas Gathering Pipeline</i>
Surface Owner <i>Multiple Producers</i>	Mineral Owner <i>NA</i>
Lease No. <i>NA</i>	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
	9	24S	26E					

Latitude: N 32.230570 Longitude: W -104.295488

**NATURE OF RELEASE**

Type of Release <i>Natural Gas</i>	Volume of Release <i>713 MCF</i>	Volume Recovered <i>0</i>
Source of Release <i>Pipeline Leak, small hole in pipe-wall.</i>	Date and Hour of Occurrence <i>10/01/2013 17:00 MDT</i>	Date and Hour of Discovery <i>10/13/2013 14:00 MDT</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>Randy Dade, District 2</i>	
By Whom? <i>Jim Heap</i>	Date and Hour <i>10/14/2013 @ 09:00 MDT</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	


If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
*Small hole in the pipe-wall; suspected corrosion fault. Loss volume includes blow-down loss for repair.*

Describe Area Affected and Cleanup Action Taken.\*  
*The line was isolated and prepped for repairs.*

**RECEIVED**  
OCT 21 2013  
NMOCD ARTESIA

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <i>Terry L. Hurlburt</i>	Approved by District Supervisor:	Signed By: 
Title: <i>Group Sr. Vice President</i>	Approval Date: <b>OCT 22 2013</b>	Expiration Date:
E-mail Address: <i>snolan@eprod.com</i>	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. <b>SUBMIT REMEDIATION PROPOSAL NO LATER THAN:</b>	Attached <input type="checkbox"/>
Date: <i>10-15-2013</i> Phone: <i>713-381-6595</i>	<b>November 22, 2013</b>	<i>2.RP-2018</i>

\* Attach Additional Sheets If Necessary  
*fJMW1329547897*  
*iJMW1329548248*




Enterprise Products™

ENTERPRISE PRODUCTS PARTNERS LP  
ENTERPRISE PRODUCTS OPERATING LLC

ENTERPRISE PRODUCTS GP, LLC, GENERAL PARTNER  
ENTERPRISE PRODUCTS OLPGP, INC., SOLE MANAGER

October 15, 2013

7012 3460 0000 1945 4699  
Return Receipt Requested



Mr. Mike Bratcher  
New Mexico Oil Conservation Division  
District 2 Office  
811 South First Street  
Artesia, New Mexico 88210

**RE: Form C-141 Report for Enterprise Field Services LLC  
Leak and Liquids Release on Carlsbad Gathering Line**

Mr. Bratcher

Enclosed, please find the requisite C-141 Forms for the unplanned releases on our White City Penn lateral on October 11, 2013 and the Pennzoil #9 A-6 Lateral line on October 13, 2013. This initial report is sent pursuant to 29 (19.15.29) NMAC and as follow-up to a verbal notifications made to Randy Dade by phone on October 11 and October 14, 2013. A final report will be completed after the repair excavation is inspected for further reportable materials (liquids).

If you have any questions or need more information, please contact Jim Heap by phone at 432-686-5404, by email at [jkheap@eprod.com](mailto:jkheap@eprod.com) or me at 713-318-6684

Regards,

(Mr)  
Jon E. Fields  
Director, Field Environmental

/sjn  
attachments