

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

RECEIVED
AUG 26 2013

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

RTMW 1329738166

Name of Company OXY USA WTP LP <i>16696</i>		Contact CAMPBELL, RODNEY
Address 329 Marathon Rd, Lakewood		Telephone No. (575) 628-4167
Facility Name INDIAN BASIN GAS PLANT		Facility Type GAS PROCESSING FACILITY
Surface Owner	Mineral Owner INDIAN BASIN	Lease No.

LOCATION OF RELEASE

Unit Letter G	Section 23	Township 21-S	Range 23-E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	----------------

Latitude 32°27'52.502" Longitude 104°34'28.004"

NATURE OF RELEASE

Type of Release Gas	Volume of Release 90 MCF	Volume Recovered 0
Source of Release Residue Flare	Date and Hour of Occurrence 8/21/2013 1:17:00 PM	Date and Hour of Discovery 8/21/2013 1:17:00 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Cause: INDIAN BASIN GAS PLANT FLARED RESIDUE SALES GAS FOR 16 MINUTES DUE TO HIGH OXYGEN CONTENT IN RESIDUE GAS STREAM. Remedial Action Taken: OPERATIONS NOTIFIED FIELD MEASUREMENT TECH. OPERATIONS CHECK INLET O2 SENSORS AND PLANT VRU WITH NORMAL OPERATIONS. SOURCE OF OXYGEN COULDN'T BE DETERMINED.		
Describe Area Affected and Cleanup Action Taken.* N/A		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>R. Campbell</i>		OIL CONSERVATION DIVISION	
Printed Name: RODNEY CAMPBELL		Approved by District Supervisor: Accepted for record NMOC	
Title: <i>HES Spec/12</i>		Approval Date: OCT 24 2013	Expiration Date:
E-mail Address: RODNEY_CAMPBELL@OXY.COM		Conditions of Approval:	
Date: <i>8-22-13</i> Phone: (575) 628-4167		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

RTMW 1327034125 *RTMW 1329739140* *2RP-2027*