District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notifica	ition and Corrective Ac	ction	
MW 1333129031	OPERATOR	Initial Report Final Report	
Name of Company Enterprise Field Services LLC 100034	77 Contact Jim Heap		
PO Box 4324, Houston, TX 77252	Telephone No. 432-686-540		
Facility Name Pipeline ROW, Baldridge Canyon Latera	al Facility Type: Gas Gatheri	ng Pipeline	
Surface Owner State of NM Mineral Ow	vner <i>NA</i>	Lease No. NA	
LOCATION OF RELEASE			
Unit Letter Section Township Range Feet from the 1 12 24S 24E	North/South Line Feet from the	East/West Line County Eddy	
Latitude: <u>N 32.225</u>	• • • •	<u>00</u>	
	JRE OF RELEASE		
Type of Release Natural Gas	Volume of Release 1,454 M		
Source of Release Pipeline Leak, small hole in pipe-wall.	Date and Hour of Occurrence	Date and Hour of Discovery 11/13/2013 16:45 MST	
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Requ	uired If YES, To Whom? Mike Bratcher, District 2		
By Whom?	Date and Hour 11/13/2013		
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse.		
If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* Small hole in the pipe-wall; suspected corrosion fault. Loss volum Describe Area Affected and Cleanup Action Taken.*	ne includes blow-down loss for repair.	NOV 2 0 2013	
The line was isolated and prepped for repairs. The hereby certify that the information given above is true and complet regulations all operators are required to report and/or file certain relevable health or the environment. The acceptance of a C-141 report should their operations have failed to adequately investigate and renor the environment. In addition, NMOCD acceptance of a C-141 refederal, state, or local laws and/or regulations.	ease notifications and perform correct by the NMOCD marked as "Final Re nediate contamination that pose a thre	ive actions for releases which may endanger port" does not relieve the operator of liability at to ground water, surface water, human health	
1: 11/11/	OIL CONS	OIL CONSERVATION DIVISIÓN	
Signature:	Approved by District Superviso	r: Signed By Mile Brance	
Title: Group Sr. Vice President	Approval Date: 2 6 2013	Expiration Date:	
E-mail Address: snolan@eprod.com	Conditions of Approval:		
Date: //-/9. 2013 Phone: 713-381-6595	Remediation per OCD Ru	. 1	
Attach Additional Sheets If Necessary FTMW 1333128849	Guidelines. SUBMIT REMED PROPOSAL NO LATER TH December 26,20	IAN: 2007	

FJMW 1333128849



RECEIVED

November 18, 2013

NOV 20 2013

7012 3460 0000 1945 3692 Return Receipt Requested

Mr. Mike Bratcher New Mexico Oil Conservation Division District 2 Office 811 South First Street Artesia, New Mexico 88210

RE:

Form C-141 Report for Enterprise Field Services LLC Leak and Liquids Release on Carlsbad Gathering Lines

Mr. Bratcher

Enclosed, please find the requisite C-141 Forms for the initial report of Eddy County releases of both gas and liquids at the following locations:

- Line 1003 on November 11, 2013.
- Line 30137 on November 12, 2013
- Baldridge Gathering line on November 12, 2013.

These reports are sent pursuant to 29 (19.15.29) NMAC and as follow-up to a verbal notifications made to Mike Bratcher by phone on November 12 and 13, 2013. Final reports for these releases will be sent when repairs have been made and the extent of liquids released can be determined.

If you have any questions or need more information, please contact Jim Heap by phone at 432-686-5404, by email at jkheap@eprod.com or me at 713-318-6684

Regards.

Ivan Zirbes

Sr. Director - Environmental

/sjn attachments