

Bratcher, Mike, EMNRD

From: Amy Ruth <aruth@diversifiedfsi.com>
Sent: Thursday, November 14, 2013 9:05 AM
To: Bratcher, Mike, EMNRD
Cc: Michael Patterson
Subject: 2RP-1733 and 2RP-1734 Turner B North Battery

Follow Up Flag: Follow up
Flag Status: Completed

Hi Mike!

Linn has excavated the entire area underneath and around the bermed battery to 4 feet, and drilled the site in 3 locations to confirm depth of impact. A reinforced liner was installed at 4 feet and the excavation was backfilled. The site was equipped with a new lined containment system and the facility was reconstructed within. The painters and welders are currently installing the last touches. I would like to talk with you about closing this site if possible though a work plan was not previously submitted. I would like to meet with you as soon as it is possible for you to review the data. Preferably by next week (Monday or Tuesday?), or sometime before Thanksgiving if you can manage that, sir.

Thank you so much for your help!!

Amy C. Ruth

Environmental Director
Diversified Field Services, Inc.
3412 N. Dal Paso
Hobbs, NM 88240
Office: (575)964-8394
Mobile: (575)390-5454
Fax: (575)964-8396

"Nothing will work unless you do." -Maya Angelou

This email and any files transmitted with it are confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify the system manager. This message contains confidential information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute or copy this e-mail. Please notify the sender immediately by e-mail if you have received this e-mail by mistake and delete this e-mail from your system. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited.