


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011
District Office in
Santa Fe, NM 87505
19.15.29 NMAC.

Release Notification and Corrective Action

NJM 1334329814

OPERATOR Initial Report Final Report

Name of Company	Oxy Permian Ltd. <i>16696</i>	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Federal 12 #1 South CTB	Facility Type	Gathering
Surface Owner	BLM	Mineral Owner	API No.30-015-26742(nearest well)

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	12	22S	31E					Eddy County, NM

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	15 bbls	Volume Recovered	0 bbls
Source of Release	Pump failure caused tank overflow	Date and Hour of Occurrence	11/20/2013	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD; Jennifer Van Curen- BLM		
By Whom?	Chancey Summers	Date and Hour	11/20/13 @ 1:00 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The electric motor on the overload connected to the pump went out causing the pump to fail and the water production tank to overflow. The overflow caused 15 bbls of produced water to leak onto the ground. No fluids were recovered and the motor was repaired/replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 30' x 30' on location. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Chancey Summers	Approved by Environmental Specialist	Signed By <i>Mike Bratcher</i>
Title:	HES Specialist	Approval Date:	DEC 04 2013 Expiration Date:
E-mail Address:	Chancey.Summers@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date:	12/3/13	Remediation per OGD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	
Phone:	(575) 397-8216	PROPOSAL NO LATER THAN:	

* Attach Additional Sheets, If Necessary

January 9, 2013

2RP-2099

Bratcher, Mike, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Wednesday, December 04, 2013 11:52 AM
To: Bratcher, Mike, EMNRD; jamos@blm.gov; jvancure@blm.gov
Cc: C J Summers; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com
Subject: Initial C-141s, Federal 12 #1 South CTB
Attachments: Initial C-141, Fed 12-1 CTB 12-2-13.pdf; Initial C-141, Fed 12#1 CTB 12-3-13.pdf

Attached are the initial C-141s for two leak that occurred at the Federal 12 #1 South CTB on 11/17/2013 and 11/20/2013 in Eddy County, NM. Receipt notification via email is greatly appreciated. I apologize for the delay due in part to the holidays.

Kathy Purvis

BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388
Fax: (575) 397-0397
Email: kathy@bbcinternational.com

Bratcher, Mike, EMNRD

From: Bratcher, Mike, EMNRD
Sent: Wednesday, December 04, 2013 2:15 PM
To: 'Kathy Purvis'; jamos@blm.gov; jvancure@blm.gov
Cc: C J Summers; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com
Subject: RE: Initial C-141s, Federal 12 #1 South CTB

C-141s received – Thanks,

Mike Bratcher
NMOCD District 2
811 S. First Street
Artesia, NM 88210
O: 575-748-1283 X108
C: 575-626-0857
F: 575-748-9720

From: Kathy Purvis [<mailto:kathy@bbcinternational.com>]
Sent: Wednesday, December 04, 2013 11:52 AM
To: Bratcher, Mike, EMNRD; jamos@blm.gov; jvancure@blm.gov
Cc: C J Summers; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com
Subject: Initial C-141s, Federal 12 #1 South CTB

Attached are the initial C-141s for two leak that occurred at the Federal 12 #1 South CTB on 11/17/2013 and 11/20/2013 in Eddy County, NM. Receipt notification via email is greatly appreciated. I apologize for the delay due in part to the holidays.

Kathy Purvis
BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388
Fax: (575) 397-0397
Email: kathy@bbcinternational.com

Bratcher, Mike, EMNRD

From: Rachael_McPherson@oxy.com
Sent: Wednesday, November 20, 2013 1:00 PM
To: jvancure@blm.gov; Bratcher, Mike, EMNRD; kathy@bbcinternational.com
Cc: Chancey_Summers@oxy.com
Subject: Federal 12 1 South CTB Battery Recordable

Oxy Permian Primary NM South had a release at the Federal 12 1 South CTB Battery on November 20, 2013. Oxy released 15 bbls of total fluid. The release is located in the Section 12 T22S, R31E of Eddy County. Oxy will conduct an initial remediation. Also BBC will delineate at a later time. A C-141 will follow. Driving directions to the release is: From 62/180 to Campbell road South go 9 miles, turn West on Caliche road, directly across from Plains Livingston Ridge Pipeline gathering station go 1.5 mile, turn South go 1.25 mile, turn East go 1500ft to location.

Thank you,

Rachael McPherson

HES Administrative Assistant
575-397-8247
Rachael_McPherson@Oxy.com

Work willingly at whatever you do, as though you were working for the Lord rather than for people. - Colossians 3:23