


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nJMW1334333986

OPERATOR Initial Report Final Report

Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Grave Digger State Com #003	Facility Type	Tank Battery
Surface Owner State	Mineral Owner	Lease No. (API#) 30-015-39151	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	02	20S	25E					Eddy

Latitude 32.609044 Longitude 104.452946

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	5bbls of oil 10bbls of produced water	Volume Recovered	3bbls of oil 6bbls of produced water
Source of Release	Fire tube on heater treater	Date and Hour of Occurrence	10-26-2013	Date and Hour of Discovery	10-26-2013 1:30pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.* A hole developed in the fire tube on the heater treater. Replaced the fire tube.					
Describe Area Affected and Cleanup Action Taken.* Initially 15bbls were released from the heater and we were able to recover 9bbls with a vacuum truck. The entire release was contained inside the lined facility. All free fluid has been recovered. Contaminated gravel has been removed from the facility. Fresh gravel has been added as necessary. The facility has been returned to its prior condition					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

OIL CONSERVATION DIVISION

Signature:	<i>Robert Grubbs Jr.</i>	Approved by District Supervisor: Signed By <i>Mike Brannon</i>	
Printed Name:	Robert Grubbs Jr.	Approval Date:	DEC 09 2013
Title:	Senior Environmental Coordinator	Expiration Date:	
E-mail Address:	rgrubbs@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date:	11-06-2013	Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	


* Attach Additional Sheets If Necessary

January 9, 2013

2RP-2101

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Wednesday, December 04, 2013 3:09 PM
To: Bratcher, Mike, EMNRD
Cc: Robert McNeill
Subject: C-141 Initial - Final Report - Grave Digger State Com #003 (TB)
Attachments: Grave Digger State Com #003 (TB) -- Date of Release -- 10-26-2013.pdf



Mr. Bratcher,

Please see attached the C-141 Initial/Final Report for a release that occurred at our Grave Digger State Com #003 (TB) on 11-19-2013 in Eddy County New Mexico. This is a lined facility.

Thank you,

*Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com*

*Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701*



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.