

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
Rio Brazos Road, Aztec, NM 87410
District IV
120 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

FEB 05 2014

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC 229 137	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Graham Cracker 16 State #003H	Facility Type	Tank Battery
Surface Owner State	Mineral Owner	Lease No. (API#) 30-015-41633	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	16	26S	28E					Eddy

Latitude 32.04922

Longitude 104.09016

NATURE OF RELEASE

Type of Release Oil	Volume of Release 155bbls	Volume Recovered 150bbls
Source of Release Oil tank	Date and Hour of Occurrence 02-03-2014	Date and Hour of Discovery 02-03-2014 08:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Michelle Mullins	Date and Hour 02-04-2014 1:50pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*



The oil tank ran over due to transport trucks did not show up. Called trucking company and told them they must be on time.

Describe Area Affected and Cleanup Action Taken.*

Initially 155bbls of oil were released due to transport trucks not showing up on time. We were able to recover 150bbls of oil with vacuum trucks. The spill was contained inside the lined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned and we has replaced with fresh gravel as necessary. This location has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION


Signature: 	Approved by District Supervisor: 	
Printed Name: Robert Grubbs Jr.	Approval Date: 3/10/14	Expiration Date: NA
Title: Senior Environmental Coordinator	Conditions of Approval: Final	
E-mail Address: rgrubbs@concho.com	Attached <input type="checkbox"/>	
Date: 02-05-2014	Phone: 432-661-6601	

* Attach Additional Sheets If Necessary

2RP 2194

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Wednesday, February 05, 2014 8:50 AM
To: Bratcher, Mike, EMNRD
Cc: Robert McNeill; Production Mail
Subject: C-141 Initial/Final Report - Graham Cracker 16 State #003H (TB)
Attachments: 02-04-2014 Graham Cracker 16 State #003H (TB) Initial - Final.pdf



Mr. Bratcher,

Please see attached the C-141 Initial/Final Report for a release that occurred at our Graham Cracker 16 State #003H (TB) on 02-04-2014 in Eddy County New Mexico. This is a lined facility.

Thank you,

**Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com
Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701**



CONFIDENTIALITY NOTICE: *The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.*

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.