District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action

R	E	C	E	1	V	D
		_	-1	_		

DEC 1 9 2013

Form C-141 Revised October 10, 2003

NMOCD APTESIA

District Office in accordance
with Rule 116 on back

side of form

nTMW 1400247338						OPERAT	Initial Report					
Name of Company COG OPERATING LLC 229/37						Contact Robert McNeill				.,po		- I I I I I I I I I I I I I I I I I I I
Address								432-230-0077				
Facility Name Down South State Com #004H						Facility Typ		Tank B				
						Tank Dancey						
Surface Owner State Mineral Owner						Lease No. (API#) 30-01					30-01	5-37256
LOCATION OF RELEASE												
Unit Letter P	Section 19	Township 26S	Range 28E	Feet from the N	North/	South Line	Feet from the	East/V	t/West Line County Eddy			
Latitude 32.02223 Longitude 104.11917												
Type of Release Oil and produced water Volume of Release 15bbls of oil Volume Recovered 0bbls of oil 0bbls oil 0bbls of oil 0bbls of oil 0bbls of oil 0bbls												
Type of Rele	ase Oil and	produced wa	ter			Volume of Release 15bbls of oil Volume Recovered 0b 25bbls of produced water 0bbls of produc					Obbls of oil oduced water	
Source of Release FWKO					Date and Hour of Occurrence Date and I				Hour of Discovery 3 3:30pm			
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required					If YES, To Whom? Mike Bratcher - NMOCD							
By Whom?	Michelle M	ullins				Date and Hour 12-10-2013 07:12am						
Was a Watercourse Reached? ☐ Yes ☑ No						If YES, Volume Impacting the Watercourse.						
If a Watercourse was Impacted, Describe Fully.*												
Describe Cause of Problem and Remedial Action Taken.*												
A gasket on a	a FWKO fa	iled. Replaced	the gaske	t to prevent a reoccu	ırrenc	e.						
Describe Are	a Affected	and Cleanup A	Action Tal	ken.*								
Initially an estimated 15bbls of oil and 25bbls of produced water were released from a gasket failure on a FWKO. We were unable to recover any fluids. The spill area is located on the location and the adjacent pasture. Concho will have the spill area sampled to delineate any possible contamination from the release and we will present a work plan to the NMOCD for approval prior to any significant remediation work.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
					OIL CONSERVATION DIVISION							
Signature:										1.1	,	
Printed Name: Robert Grubbs Jr.						Approved by District Supervisor; igned By_Mily Branches						
Title:	Title: Senior Environmental Coordinator					Approval Date: Lexpiration Date:						
E-mail Addre	ess:	rgrubbs@	gconcho.c	om	_	Conditions of	litions of Approval:		Attached	Attached		
	19-2013	ICX	Phone:	432-661-6601			A					
Attach Additional Sheets If Necessary						Remediation per OCD Rule & 22P-21					2179	

Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:

Bratcher, Mike, EMNRD


From: Robert Grubbs <RGrubbs@concho.com>
Sent: Thursday, December 19, 2013 4:09 PM

To: Bratcher, Mike, EMNRD

Cc: Robert McNeill; Tavarez, Ike; Kujawski, Marcus (Marcus.Kujawski@tetratech.com)

Subject: C-141 Initial Report - Down South State Com #004H (TB)

Attachments: Down South State Com #004H (TB) -- Date of Release -- 12-08-2013.pdf



Mr. Bratcher,

Please see attached the C-141 Initial Report for a release that occurred at our Down South State Com #004H (TB) on 12-08-2013 in Eddy County New Mexico. We plan to assess the spill area timely.

Thank you,

Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com
Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From:

Michelle Mullins < MMullins@concho.com>

Sent:

Tuesday, December 10, 2013 6:12 AM

To:

Bratcher, Mike, EMNRD

Cc:

Robert Grubbs

Subject:

Down South State Com #4H-Immediate Notification

Mr. Bratcher:

At approximately 3:30 p.m. on 12/08/2013, a produced fluid release was discovered at the above-referenced facility. An estimated 40 bbls of produced fluid was released. The cause of the release is currently under investigation. We will follow up within 15 days with a C-141 Report. GPS coordinates, legal description and driving directions are listed below.

32.02223 104.11917

Down South State Com #4H Unit P Sec 19 T26S R28E 660' FSL & 330' FEL Eddy County, NM API 30-015-37256

From Artesia, travel south on Highway 285 to MM 5. (White City Road). Turn west, and travel approximately 3.5 miles. Turn south and travel approximately 3 miles. Battery is on the west side of lease road.

Thank you.

Michelle Mullins
Environmental Coordinator
COG Operating, LLC
(432) 934-1052
mmullins@concho.com

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.