


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW1401637206

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC 229/37	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Sherman 4 Fee #004	Facility Type	Tank Battery
Surface Owner	Private	Mineral Owner	
		Lease No. (API#)	30-015-39720

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	04	19S	26E					Eddy

Latitude 32.68295 Longitude 104.38141

NATURE OF RELEASE

Type of Release	Oil and water	Volume of Release	8bbls of oil 1bbl of produced water	Volume Recovered	7bbls of oil 1/2 bbl of produced water
Source of Release	Site glass	Date and Hour of Occurrence	12-27-2013	Date and Hour of Discovery	12-27-2013 07:15am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Gauge cocks did not hold the site glass in place, causing the site glass to break. Replaced gauge cocks and site glass.

Describe Area Affected and Cleanup Action Taken.*

Initially 8bbls of oil and 1bbl of produced water were released due a broken site glass on a separator. We were able to recover 7bbls of oil and 1/2bbl of produced water with a vacuum truck. The spill was contained inside the lined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned and we has replaced with fresh gravel as necessary. This location has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.		Approved by District Supervisor Signed By	
Title: Senior Environmental Coordinator		Approval Date: JAN 16 2014	Expiration Date:
E-mail Address: rgrubbs@concho.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 01-02-2014	Phone: 432-661-6601		


* Attach Additional Sheets If Necessary

Accepted for record
NMOCD

2RP-2146

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Thursday, January 02, 2014 12:26 PM
To: Bratcher, Mike, EMNRD
Cc: Robert McNeill
Subject: C-141 Initial/Final Report - Sherman 4 Fee #004 (TB)
Attachments: Sherman 4 Fee #004 (TB) -- Date of Release -- 12-27-2013.pdf



Mr. Bratcher,

Please see attached the C-141 Initial/Final Report for a release that occurred at our Sherman 4 Fee #004 (TB) on 12-27-2013 in Eddy County New Mexico. This is a lined facility.

Thank you,

Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com
Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701



CONFIDENTIALITY NOTICE: *The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.*