


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

229137 **OPERATOR** ☒ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Lakewood SWD #004	Facility Type	SWD
Surface Owner	Private	Mineral Owner	
		Lease No. (API#)	30-015-26270

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	06	19S	26E					Eddy

Latitude 32.688088 Longitude 104.42768

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	40bbls	Volume Recovered	40bbls
Source of Release	Water leg on gun barrel	Date and Hour of Occurrence	12-25-2013	Date and Hour of Discovery	12-25-2013 08:00am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - NMOCD		
By Whom?	Michelle Mullins	Date and Hour	12-26-2013 07:40am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
Water leg on gun barrel developed a leak around the bottom collar. The collar has been replaced.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 40bbls of produced water were released from the water leg on the gun barrel. We were able to recover 40bbls with a vacuum truck. The release was completely contained inside the lined facility walls of the tank battery. All free fluid has been recovered. Any contaminated gravel has been removed and we have replaced with fresh gravel as necessary. The facility has been returned to its prior condition.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: <i>Robert Grubbs Jr.</i>		OIL CONSERVATION DIVISION			
Printed Name: Robert Grubbs Jr.		Approved by District Supervisor Signed By <i>Mike Bratcher</i>			
Title: Senior Environmental Coordinator		Approval Date: JAN 16 2014		Expiration Date:	
E-mail Address: rgrubbs@concho.com		Conditions of Approval:		Attached <input type="checkbox"/>	
Date: 01-15-2014 Phone: 432-661-6601					

* Attach Additional Sheets If Necessary

Accepted for record
NMOCD

2RP-2147

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Wednesday, January 15, 2014 9:51 AM
To: Bratcher, Mike, EMNRD
Cc: Robert McNeill
Subject: C-141 Initial/Final Report - Lakewood SWD #004
Attachments: Lakewood SWD #004 (SWD) -- Date of release -- 12-25-2013.pdf



Gentlemen,

Please see attached the C-141 Initial/Final Report for a release that occurred at our Lakewood SWD #004 on 12-25-2013 in Eddy County New Mexico. This is a lined facility.

Thank you,

Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com
Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701



CONFIDENTIALITY NOTICE: *The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.*

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that

any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Thursday, January 02, 2014 12:07 PM
To: Bratcher, Mike, EMNRD; Mike Burton (mburton@blm.gov) (mburton@blm.gov); Amos, James <jamos@blm.gov> (jamos@blm.gov)
Cc: Robert McNeill
Subject: C-141 Initial/Final Report - Lakewood SWD #4
Attachments: Lakewood SWD #4 (SWD) -- Date of Release -- 12-25-2013.pdf



Gentlemen,

Please see attached the C-141 Initial/Final Report for a release that occurred at our Lakewood SWD #4 on 12-25-2013 in Eddy County New Mexico. This is a lined facility.

Thank you,

Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com
Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701



CONFIDENTIALITY NOTICE: *The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.*

Bratcher, Mike, EMNRD

From: Michelle Mullins <MMullins@concho.com>
Sent: Thursday, December 26, 2013 6:40 AM
To: Bratcher, Mike, EMNRD
Cc: Robert Grubbs
Subject: Lakewood SWD #4-Immediate Notification

Mr. Bratcher:

At approximately 8:00 a.m. on 12/25/2013, a produced fluid release was discovered at the above-referenced facility. An estimated 40 barrels of produced fluid was released. The cause of the release is currently under investigation. We will follow up within 15 days with a C-141 Report. GPS coordinates, legal description and driving directions are listed below.

32.68808 104.42768

Lakewood SWD #4
Unit L Sec 6 T19S R26E
1953' FSL & 663' FWL
Eddy County, NM
API 30-015-26270

On Highway 285, travel south from Artesia. Turn west onto Kincaid Ranch Road (CR 38) and travel 2.7 miles. Turn south and travel .9 miles. Turn east and travel .8 miles. Turn south and travel .6 miles. Location is on the east side of lease road.

Michelle Mullins
Environmental Coordinator
COG Operating, LLC
(432) 934-1052
mmullins@concho.com

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.