


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

njmw 1402138673

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd. <i>16696</i>	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Cypress 34 Federal #1CTB	Facility Type	Gathering
Surface Owner	BLM	Mineral Owner	
		API No.	30-015-35053 (nearest well)

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	34	23S	29E	460	South	660	East	Eddy

Latitude N 32.25496° Longitude W 103.96596°

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	90 bbls	Volume Recovered	80 bbls
Source of Release	Kimray dump valve failed on 3 phase separator causing tanks to spill over	Date and Hour of Occurrence	12/21/2013	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The failure of a Kimray dump valve on a 3 phase separator caused the tanks to spill 90 bbls of oil onto the ground. 80 bbls of oil were recovered via vacuum truck and the valve was repaired or replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 30' x 90' on location. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Chancey Summers		Approved by Environmental Specialist: <i>Mike Brannon</i>	
Title: HES Specialist		Approval Date: JAN 21 2014	Expiration Date:
E-mail Address: <u>Chancey.Summers@oxy.com</u>		Conditions of Approval:	Attached <input type="checkbox"/>
Date: <u>1-8-14</u>	Phone: (575) 397-8216	Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: February 21, 2014	

* Attach Additional Sheets If Necessary

2RP-2151

Bratcher, Mike, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Wednesday, January 08, 2014 8:58 AM
To: Bratcher, Mike, EMNRD; jvancure@blm.gov
Cc: C J Summers; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com
Subject: Initial C-141, Cypress 34 Federal #1 CTB
Attachments: Initial C-141, Cypress 34 Fed #1 CTB.pdf

Attached is the initial C-141 for a leak that occurred at the Cypress 34 Federal #1 CTB on 12/21/2013 in Eddy County, NM. Receipt notification via email is greatly appreciated.

Kathy Purvis
BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388
Fax: (575) 397-0397
Email: kathy@bbcinternational.com

Bratcher, Mike, EMNRD

From: Rachael_McPherson@oxy.com
Sent: Monday, December 30, 2013 1:28 PM
To: Bratcher, Mike, EMNRD; jvancure@blm.gov
Cc: Chancey_Summers@oxy.com
Subject: Cypress 34 Federal 1 CTB Battery

Oxy Permian Primary NM South had a release at the Cypress 34 Federal 1 CTB Battery on December 21, 2013. This leak was verbally called in on Thursday December 26th. The release is located in the Sect 24 T23S R29E of Eddy County. Oxy will be conducting an initial remediation. BBC will delineate at a later date. A C-141 will follow. Driving Directions to release: South out of Carlsbad on 285 7.5 miles turn West on CR 31 go 4 miles turn East on hwy 128 turn South on Rawhide road till rd turns to caliche take 2nd right go 5.5 miles due west after Oxy sign, turn South for 2 miles cross over 2 cattle guards and location is on top of hill on North side of road.

Thank you,

Rachael McPherson

HES Administrative Assistant
575-397-8247
Rachael_McPherson@Oxy.com

Work willingly at whatever you do, as though you were working for the Lord rather than for people.- Colossians 3:23