


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NHMP1406637338 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Amber Cannon
Address 105 S. 4 TH Street	Telephone No. 575-748-1471	
Facility Name Dolores AIL Federal #2 (Livingston Ridge)	API Number 30-015-26548	Facility Type Flow line
Surface Owner Federal	Mineral Owner Federal	Lease No. NM-65418

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	14	22S	31E	1980'	South	430'	East	Eddy

Latitude 32.3896 Longitude 103.74089

NATURE OF RELEASE

Type of Release Produced Water; Crude Oil	Volume of Release 99 B/PW; 1 B/O	Volume Recovered 75 B/PW; 1 B/O
Source of Release Water transfer line ruptured	Date and Hour of Occurrence 2/4/2014	Date and Hour of Discovery 2/4/2014
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, NMOCD District II	
By Whom? Robert Asher, Yates Petroleum Corporation	Date and Hour 2/5/2014	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		

Describe Cause of Problem and Remedial Action Taken.*
A poly pipe (water transfer line) ruptured

Describe Area Affected and Cleanup Action Taken.*

An approximate area of 20' X 30'. Spill is approximately 200 yards north of cattle guard where CR29 intersects. The release occurred over the same area as a release from 8/17/2013 (this release was still in the process of being cleaned up). The release made a flow path on the east side of the lease road. The flow line valves were shut off, leak was isolated, and Dolores water pump was shut off. The line was repaired. Flow path on the east side of the lease road will be excavated. All excavated soils will be disposed of at an approved NMOCD facility. Vertical and horizontal delineation samples will be taken and sent to a NMOCD approved facility. Depth to Ground Water: >100' (approximately 150', Section 11, T22S-R31E, per Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Amber Cannon</u>		OIL CONSERVATION DIVISION	
Printed Name: Amber Cannon		Approved by District Supervisor: <u>Heidi Cannon</u>	
Title: Environmental Regulatory Agent		Approval Date: <u>3/7/14</u>	Expiration Date:
E-mail Address: <u>acannon@yatespetroleum.com</u>		Conditions of Approval:	
Date: Thursday, February 20, 2014 Phone: 575-748-4111		Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <u>4/7/14</u>	
		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP 2188

Bratcher, Mike, EMNRD

From: Amber Cannon <ACannon@yatespetroleum.com>
Sent: Thursday, February 20, 2014 8:00 AM
To: Bratcher, Mike, EMNRD; Duncan Whitlock
Subject: RE: Release (Livingston Ridge Water System/Deloris AIL Federal #2)
Attachments: DoloresAILFederal2_LivingstonRidge_C141_02-04-14 Initial.pdf

Please find attached an initial C-141 for the release mentioned below.

Thanks,
Amber

From: Bob Asher
Sent: Wednesday, February 05, 2014 10:57 AM
To: (mike.bratcher@state.nm.us); (Randy.Dade@state.nm.us); jamos@blm.gov
Cc: Amber Cannon; Chase Settle; Katie Parker; Lupe Carrasco
Subject: Release (Livingston Ridge Water System/Deloris AIL Federal #2)

Yates Petroleum Corporation is reporting a release at the following location (2/4/2014).

Livingston Ridge Water System (Dolores AIL Federal #2)
30-015-26548
Section 14, T22S-R31E
Eddy County, New Mexico

Released: Approximately 100 B/PW; Recovered: Unknown at this time.

Cause of release is from a pipe line. Well(s) shut in. Release area isolated. Vacuum truck(s) and backhoe crew were called.

Please note that the release point is within the same area as the 8/12/2013 release (see attached map).

A Form C-141 Initial will be submitted with complete information.

Thank you.

Robert Asher
NM Environmental Regulatory Supervisor
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed,

arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.

Bratcher, Mike, EMNRD

From: Bob Asher <BobA@yatespetroleum.com>
Sent: Wednesday, February 05, 2014 10:57 AM
To: Bratcher, Mike, EMNRD; Dade, Randy, EMNRD; jamos@blm.gov
Cc: Amber Cannon; Chase Settle; Katie Parker; Lupe Carrasco
Subject: Release (Livingston Ridge Water System/Deloris AIL Federal #2)
Attachments: Livingston Ridge SWD Water Line 020414 Release.pdf

Yates Petroleum Corporation is reporting a release at the following location (2/4/2014).

Livingston Ridge Water System (Dolores AIL Federal #2)
30-015-26548
Section 14, T22S-R31E
Eddy County, New Mexico

Released: Approximately 100 B/PW; Recovered: Unknown at this time.

Cause of release is from a pipe line. Well(s) shut in. Release area isolated. Vacuum truck(s) and backhoe crew were called.

Please note that the release point is within the same area as the 8/12/2013 release (see attached map).

A Form C-141 Initial will be submitted with complete information.


Thank you.

Robert Asher

NM Environmental Regulatory Supervisor

Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.



Google earth

feet 900
meters 200

