

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*nHMP 1410127289*

<b>OPERATOR</b>		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: BOPCO, L.P. <i>260737</i>		Contact: Tony Savoie	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 575-887-7329	
Facility Name: PLU-50 Tank Battery and well		Facility Type: Exploration and Production	

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-23283
------------------------	------------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	4	25S	31E	660	North	1980	East	Eddy

Latitude N 32.164930 Longitude W 103.780630

**NATURE OF RELEASE**

Type of Release: Produced water	Volume of Release: 10 bbls water	Volume Recovered: none
Source of Release: Water storage tank	Date and Hour of Occurrence 3/27/14 time unknown	Date and Hour of Discovery 3/27/14 at 2:05 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? The NMOCD emergency #104	
By Whom? Tony Savoie	Date and Hour: 3/27/14 at 3:00 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		<div style="border: 1px solid black; padding: 5px; text-align: center;">RECEIVED APR 09 2014 NMOCD ARTESIA</div>

Describe Cause of Problem and Remedial Action Taken.\* The water production tank overflowed due to a contract trucking company failed to haul water from the facility

Describe Area Affected and Cleanup Action Taken.\*

Nearly the entire area inside the earthen containment was impacted by this release and a prior release on 7/3/13. Reference 2RP-1728. The containment area measures approximately 2700 sq.ft. The tank battery will be dismantled and a new 0 perm containment will be constructed on the well pad area. The tanks will be placed in the new containment and the old tank battery location will be cleaned up. By spill area will be remediated in accordance to the NMOCD and BLM guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie		Approved by Environmental Specialist: <i>Huber</i>	
Title: Waste Management and Remediation Specialist		Approval Date: <i>4/11/14</i>	Expiration Date: <i>NA</i>
E-mail Address: <i>tasavoie@basspet.com</i>		Conditions of Approval:	
Date: 4/9/14 Phone: 432-556-8730		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

Remediation per OCD Rule &  
Guidelines. **SUBMIT REMEDIATION  
PROPOSAL NO LATER THAN:**

*5/11/14*

*2RP-2257*