

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
100 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

APR 10 2014

NMOCD ARTE

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nHMP1410542326

OPERATOR

☒ Initial Report ☒ Final Report

| | | | |
|-----------------|---|------------------|----------------|
| Name of Company | COG OPERATING LLC 229137 | Contact | Robert McNeill |
| Address | 600 West Illinois Avenue, Midland, TX 79701 | Telephone No. | 432-230-0077 |
| Facility Name | Burch Keely Unit #386 | Facility Type | Tank Battery |
| Surface Owner | Federal | Mineral Owner | |
| | | Lease No. (API#) | 30-015-33797 |

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| G | 13 | 17S | 29E | | | | | Eddy |

Latitude 32 50.171

Longitude 104 01.573

NATURE OF RELEASE

| | | |
|---|---|---|
| Type of Release Produced water | Volume of Release 10bbls | Volume Recovered 8bbls |
| Source of Release Heater treater | Date and Hour of Occurrence 03-27-2014 | Date and Hour of Discovery 03-27-2014 4:00pm |
| Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required | If YES, To Whom? | |
| By Whom? | Date and Hour | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |

a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*


A 90 degree elbow developed a hole in the bottom. Replaced the 90 degree elbow on the bottom of the heater treater.

Describe Area Affected and Cleanup Action Taken.*

Initially 10bbls of produced water were released. We were able to recover 8bbls with a vacuum truck. The spill was contained inside the lined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned and we has replaced with fresh gravel as necessary. This location has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 
Printed Name: Robert Grubbs Jr.
Title: Senior Environmental Coordinator
E-mail Address: rgrubbs@concho.com

Approved by District Supervisor: 

Approval Date: 4/15/14

Expiration Date: NA

Conditions of Approval:

Final

Attached ☐

Date: 04-09-2014 Phone: 432-661-6601

Attach Additional Sheets If Necessary

2RP-2261

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Thursday, April 10, 2014 1:01 PM
To: Mike Burton (mburton@blm.gov) (mburton@blm.gov); Bratcher, Mike, EMNRD
Cc: Robert McNeill
Subject: C-141 Initial/Final Report - Burch Keely Unit #386 (TB)
Attachments: 03-27-2014 Burch Keely Unit #386 (TB) Initial - Final.pdf



Mr. Bratcher,

Please see attached the C-141 Initial/Final Report for a release that occurred at our Burch Keely Unit #386 (TB) on 03-27-2014 in Eddy County New Mexico. This is a lined facility.

Thank you,

Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com

Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701



CONFIDENTIALITY NOTICE: *The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.*

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.