

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	COG Operating LLC	Contact	Pat Ellis
Address	550 W. Texas, Suite 1300 Midland, Texas 79701	Telephone No.	(432) 230-0077
Facility Name	BKU Central Tank Battery	Facility Type	Tank Battery
Surface Owner	Federal	Mineral Owner	
		Lease No.	30-015-29809

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	23	17-S	29-E					Eddy

Latitude N 32 49.161° Longitude W 104 01.546°

NATURE OF RELEASE

Type of Release: Oil	Volume of Release 120 bbls	Volume Recovered 115 bbls
Source of Release Oil Tank	Date and Hour of Occurrence 12/03/2011	Date and Hour of Discovery 12/03/2011 6:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - OCD Jim Amos - BLM Terry Gregston - BLM	
By Whom? Josh Russo	Date and Hour 12/05/2011 8:48 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* A hole developed in an oil tank at the facility causing the release. The tank was isolated and has been prepared for repairs.		
Describe Area Affected and Cleanup Action Taken.* Tetra Tech inspected and collected samples to define spill extents. Soil with elevated chloride concentrations was removed and transported to Controlled Recovery, Inc. for proper disposal. Once excavated to the appropriate depths, the site was backfilled with clean soil and then brought up to surface grade. Tetra Tech prepared and submitted the closure report to NMOCD for review.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ike Tavarez (agent for COG)	Approved by District Supervisor: 	
Title: Project Manager	Approval Date: APR 17 2014	Expiration Date: NA
E-mail Address: ike.tavarez@tetrattech.com	Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: 8/15/12 Phone: (432) 682-4559		

* Attach Additional Sheets If Necessary