1625 N. French Dr., Hobbs, NM 88240Energy MinerDistrict IIDistrict III1000 Rio Brazos Road, Aztec, NM 87410Oil CorDistrict IV1220 Sc1220 S. St. Francis Dr., Santa Fe, NM 87505Santa	e of New Mexico erals and Natural Resource mservation Division South St. Francis Dr. ta Fe, NM 87505 RECEIVED MAR 1 3 2013 Bubmit District Office in accordance with Rule 116 on back side of form Action	
	OPERATOR Initial Report A Final Report	
Name of Company COG Operating LLC	Contact Pat Ellis	
Address 550 W. Texas, Suite 1300 Midland, Texas 7970		
Facility Name JR's Horz Federal Tank Battery	Facility Type Tank Battery	
Surface Owner: Federal Mineral Own	ner Lease No. NMNM-92177	
LOCATION OF RELEASE		
Unit LetterSectionTownshipRangeFeet from theND1026S29E380	North/South LineFeet from theEast/West LineCountyNorth330WestEddy	
Latitude N 32.063	344° Longitude W 103.97959°	
NATURE OF RELEASE		
Type of Release: Oil	Volume of Release 328 bbls Volume Recovered 161 bbls	
Source of Release: Oil Tanks	Date and Hour of OccurrenceDate and Hour of Discovery11/10/201011/10/20108:30 a.m.	
Was Immediate Notice Given?	11/10/2010 11/10/2010 8:30 a.m. If YES, To Whom? 11/10/2010 11/10/2010	
Yes 🗌 No 🗌 Not Requi		
By Whom? Josh Russo	Date and Hour 11/11/2010 8:24 a.m.	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.*		
Oil overflowed out of oil storage tanks due to water flow from JR's Horz #1 well backside. JR's Horz #1 well has had tubing and casing shut in until further notice.		
Describe Area Affected and Cleanup Action Taken.*		
Tetra Tech personnel inspected the site and collected samples to define the spills extent. Soil that exceeded RRAL was removed and hauled away for proper disposal. The site was then brought up to surface grade with clean backfill material. Tetra Tech prepared a closure report and submitted it to NMOCD for review.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
/ MAT 1	OIL CONSERVATION DIVISION	
Signature:	Approved by District Supervisor:	
Printed Name: Ike Tavarez (Agant to COG)	+ i/m cm	
Title: Project Manager	Approval Date: $U/21/10/$ Expiration Date: NA	
E-mail Address: lke.Tavarez@TetraTech.com	Conditions of Approval:	
Date: 2 13-13 Phone: (432) 682-4559	En a	
Attach Additional Sheets If Necessary	2RP-480	