

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nHMP1411828179		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: BOPCO, L.P.		260737		Contact: Tony Savoie	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220				Telephone No. 575-887-7329	
Facility Name: Delaware "C" Tank Battery, same well pad as the PLU-153				Facility Type: Exploration and Production	

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-31412
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter G	Section 6	Township 24S	Range 30 E	Feet from the 1830	North/South Line North	Feet from the 1980	East/West Line East	County Eddy
------------------	--------------	-----------------	---------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude N 32.248866 Longitude W 103.919096

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 200 bbls	Volume Recovered: 15 bbls
Source of Release: 3" SWD injection line	Date and Hour of Occurrence: 4/21/14 time unknown	Date and Hour of Discovery: 4/21/14 at 12:30 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency #104 and the BLM	
By Whom? Tony Savoie	Date and Hour: 4/21/14 at 2:30 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*	RECEIVED APR 24 2014
---	--------------------------------

Describe Cause of Problem and Remedial Action Taken.* A 3" high pressure fiberglass line coupling broke in the coupling threads. The connection was replaced.	NMOCD ARTESIA
--	----------------------

Describe Area Affected and Cleanup Action Taken.* The spill impacted approximately 4000 sq.ft. of pad area at the SWD location, approximately 4200 sq.ft. of pasture area and approximately 1300 sq.ft. of lease road. The spill ponded and followed a spill path almost identical to a spill at the same pump location on 5/30/12 reference 2RP-1205. The SWD is scheduled to be dismantled and the oil production battery re-located this year. There are several open C-141's for this facility that will be addressed at the time the battery is re-located.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Waste Management and Remediation Specialist		Approval Date: <i>4/28/14</i>	Expiration Date: <i>NA</i>
E-mail Address: <i>tasavoie@basspet.com</i>		Conditions of Approval:	
Date: 4/24/14 Phone: 432-556-8730		Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	
		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:

5/28/14

2RP-2264

PLU-Del C SWD

©2014 Google

Go

1996

Imagery Date: 2/13/2014 lat: 32.248780° lon: -103.918559° elev: 3261 ft