

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

aHMP 1411829494

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: BOPCO, L.P. <i>260 737</i>		Contact: Tony Savoie	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 575-887-7329	
Facility Name: PLU-162		Facility Type: Exploration and Production	

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-35522
------------------------	------------------------	----------------------


LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	6	24S	30E	660	North	1855	West	Eddy

Latitude N 32.252159 **Longitude** W 103.923572

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 400 bbls	Volume Recovered: None
Source of Release: 1" hose on the water injection line	Date and Hour of Occurrence: 4/20/14 time unknown	Date and Hour of Discovery: 4/20/14 at 5:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency #104 and the BLM	
By Whom? Tony Savoie	Date and Hour: 4/20/14 at 9:00 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		



Describe Cause of Problem and Remedial Action Taken.*

A 1" high pressure hose connecting the flow line to the well failed at the coupling. The hose section was replaced.

Describe Area Affected and Cleanup Action Taken.*

The spill impacted approximately 22,500 sq.ft. of well pad area and approximately 15,000 sq.ft. of pasture area. The site was cleared by the BLM Arch survey. Basin Environmental began delineation activities on 4/21/14 and started removing impacted soil on 4/22/14. The remediation is in progress. The spill will be cleaned up in accordance to the NMOCD and BLM remediation guidelines.


I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION	
Signature: <i>Tony Savoie</i>	Approved by Environmental Specialist: <i>[Signature]</i>
Printed Name: Tony Savoie	Approval Date: <i>4/28/14</i> Expiration Date: <i>NA</i>
Title: Waste Management and Remediation Specialist	Conditions of Approval:
E-mail Address: <i>tasavoie@basspet.com</i>	Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:
Date: 4/24/14 Phone: 432-556-8730	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

5/25/14

2RP-2265



Legend:

—— Release Margins

Figure 1
Release Margins Map
BOPCO, L.P.
Poker Lake Unit #162
Eddy County, New Mexico

Basin Environmental Services

Prep By: JWL

Checked By: BJA

April 21, 2014

Scale 1"=100'

Savoie, Tony A.

From: Amos, James <jamos@blm.gov>
Sent: Monday, April 21, 2014 4:31 PM
To: Joel Lowry
Cc: Savoie, Tony A.; Walters, Sherman J.; bjarguijo@basinenv.com
Subject: Re: BOPCO's PLU #162 Release Site -- BLM Spill Margins Map

Folks,

I've reviewed the arch, and you are clear to proceed with sampling etc. Keep me in the loop. thanks

On Mon, Apr 21, 2014 at 1:56 PM, Joel Lowry <jwlowry@basinenv.com> wrote:

Please find attached a Site Location Map and Release Margins Map that have been prepared for BOPCO's PLU #162 Release. I walked the margins of the release site with a GPS earlier today. We are hoping that this information will be helpful in determining whether an Arch Survey needs to be conducted before we can begin remediation activities.

Ben Arguijo indicated that he spoke to you earlier regarding this site. These maps are supplements to that conversation. Thanks.

Respectfully,

Joel Lowry

--

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

James A. Amos
Bureau of Land Management
Carlsbad Field Office
Supervisory Environmental Protection Specialist
620 East Greene Street
Carlsbad, NM. 88220
Office: (575) 234-5909

