

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

APR 29 2014

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

NMOCD ARTE

Release Notification and Corrective Action

nHMP1412133862

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	16696	Contact	CJ Summers
Address	1017 W. Stanolind Rd, Hobbs, NM		Telephone No.	(575) 397-8216
Facility Name	Cypress 33 Federal #6H		Facility Type	Well location
Surface Owner	BLM	Mineral Owner	API No. 30-015-41557	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	33	23S	29E	466	North	1040	East	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	5 bbls oil, 195 bbls produced water	Volume Recovered	50 bbls
Source of Release	PRD did not reset on production flow line	Date and Hour of Occurrence	04/28/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD; Jennifer Van Curen-BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	04/28/14 @ 4:36 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A PRD on a production flow line did not reset and caused 195 bbls of produced water and 5 bbls of oil to leak onto the ground. A total of 10 bbls of fluids were recovered via vacuum truck and the PRD was repaired/replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 400' x 80' on and off location. Remediation will be completed in accordance a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Chancey Summers	Approved by District Supervisor: 	
Title: HES Specialist	Approval Date: 5/1/14	Expiration Date: NA
E-mail Address: Chancey.Summers@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4-29-14	Phone: (575) 397-8216	

* Attach Additional Sheets If Necessary

Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:

6/1/14

2PP-2273