District I 1625 N. French Dr., Hobbs, NM 88240 District II				State of New Mexico Energy Minerals and Natural Resources					Form C-141 Revised August 8, 2011				
811 S. First St., Artesia, NM 88210District III1000 Rio Brazos Road, Aztec, NM 87410District IV1220 S. St. Francis Dr., Santa Fe, NM 87505			5	. 1220	South	vation Div St. Franc	Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.						
1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505 Release Notification and Corrective Action													
Hong	241100	7110511-		ease notific				ction		10		E' 1 D	
n HMP14/2240947 Name of Company: Aquila Drilling-BOPCO, L.P. 260737						OPERATOR Initial Report Final Report Final Report Final Report							
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 Telephone No. BOPCO 575-887-7329, Aquila 940-761-3153													
Facility Name: JRU-21 SWD-1 Facility Type: Drilling Rig													
Surface Ow	mer: Feder	al	Mineral C	wner: F	Federal API No. 30-015-41074								
LOCATION OF RELEASE Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County													
Unit Letter G						South Line th	East/West Line East		County Eddy				
Latitude <u>N 32.381464</u> Longitude <u>W 103.883210</u>													
NATURE OF RELEASE Type of Release: Diesel Volume of Release: 1000 gallons Volume Recovered: 400 gallons													
Type of Release: Diesel Source of Release: Bulk Storage 1" hose							Release: 1000 ga lour of Occurrenc			Recovered: 4 Hour of Dis			
						1/13/14 approximately 5:00 a.m. 1/13/14 at approximately 5:00 a.m.							
Was Immediate Notice Given?						If YES, To Whom? ed Mike Bratcher NMOCD, Jim Amos BLM, John Wells NMED							
By Whom? Tony Savoie						Date and Hour: NMOCD 1/13/14 at 10:33 a.m., BLM at 10:57a.m., NMED at 11:00 a.m.							
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse. RECEN					EIV	'ED	
If a Watercourse was Impacted, Describe Fully.*						APR 2 9 2014							
MOCD ARTESIA													
Describe Cause of Problem and Remedial Action Taken.* Fuel was being transferred via a 1" hose, the hose was laid on the ground un-attended and the valve was left open. The valve was closed upon discovery.													
Describe Area Affected and Cleanup Action Taken.* The spill impacted and area approximately 50 ft. X 50 ft. around the diesel storage tanks and approximately 185 ft. of containment ditch that had been dug around the tanks and generators. Approximately 400 gallons of diesel was recovered, remediation will take place after the rig, tanks and generators have been removed. The rig moved off location on 4/20/14. DFSI, will begin remediation activities on 4/29/14. The waste generated by the spill will be tested to determine the complete waste characteristics before moving off-site The spill area will be cleaned up in accordance to the NMOCD, BLM and NMED remediation guidelines.													
regulations a public health should their or the enviro	Il operators or the envioperations homent. In a	are required t ronment. The nave failed to	to report and acceptane adequately OCD accept	e is true and comp nd/or file certain r ce of a C-141 repo v investigate and r otance of a C-141	elease no ort by the emediate	otifications a NMOCD m e contaminati	nd perform correc arked as "Final R ion that pose a thr	tive act eport" of eat to g	tions for rel does not rel round wate	eases which ieve the ope r, surface wa	may er erator of ater, hu	ndanger f liability man health	
						OIL CONSERVATION DIVISION							
Signature: 1 Bry Danie													
Printed Name: Tony Savoie Printed Name: Clay Gordy Operations Mgr. for Aquila						Approved by Environmental Specialist:							
	•	nt and Remed		•		Approval Da	te: 5/2/14	·	Expiration	Date: 1	1A		
E-mail Address: tasavoie@basspet.com						Conditions o	f Approval:			Attachec	 1 []		
Date: 4/24/14 4/29/14 Phone: 432-556-873(per OCD Rule 8 by BLM. <u>SUBMI</u>			7 machet			
* Attach Additional Sheets If Necessary						PROPOSAL NO LATER THAN: ZRP-2285							
								· · ·			•		