District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

**HOBBS OCD** 

Form C-141 Revised October 10, 2003

MAR 2 6 2014
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form.

Release Notification and Corrective Action /													
			<u> </u>		TOR	·	X	Initial	Report		Final Report		
Name of Co		oration		OGRID Nun 25575	* .	Contact	A .						
Yates Petroleum Corporation 25575 Address						Chase Settle , Telephone No.							
104 S. 4 <sup>TH</sup> S		<del></del>	34	575-748-4171									
Facility Name API No Rider BRQ Federal #2-H 30-025-						Facility Type						,	
,		/-In		Battery									
Surface Ow Federal	ner		Mineral Owner Federal						Lease No. NMNM-108476				
LOCATION OF RELEASE													
Unit Letter Section Township M 13 25S			Range 34E	Feet from the 330'	North/	South Line South	The state of the s		est Line est	**************************************			
Latitude 32.12399 Longitude -103.42961													
NATURE OF RELEASE													
Type of Release Gas, Crude Oil, and Produced Water						Volume of Release 7 B/O, 8 B/PW, 20 MCF/G			Volume Recovered				
Source of Release						Date and Hour of Occurrence			4 B/O & 3 B/PW, 0 MCF/G  Date and Hour of Discovery				
Casing valve Was Immedi		Given?	<del>,</del>	03/13/2014; AM 03/13/2014; AM If YES, To Whom?						<u> </u>			
was infilled	iate Notice v	Given:	equired										
By Whom?						Date and Hours							
N/A Was a Water	rcourse Rea	ched?	<u> </u>	If YES, Volume Impacting the Watercourse.									
If a Waterco	urse was Im	pacted, Descr		N/A									
N/A $D/W = 1.30$													
Describe Cause of Problem and Remedial Action Taken.* Casing valve failure allowed crude oil, produced water, and gas to be released on to the location pad.													
	Describe Area Affected and Cleanup Action Taken.*												
An approximate area of 50' X 60' was affected on the location between the wellhead and battery. Vacuum truck was procured to remove standing fluid, and backhoe used to remove impacted soils. Impacted soils were excavated and hauled to NMOCD approved facility. Vertical and horizontal delineation													
samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's (site ranking is 0) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL a work plan will be													
submitted to the OCD. Depth to Ground Water: >100' (165', Section 13, T25S-R34E, Trend Map), Wellhead Protection Area: No, Distance to													
Surface Water Body: > 1000;, SITE RANKING IS 0.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger													
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability, should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the environment: In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
				OIL CONSERVATION DIVISION									
Signature		-		SEXPLOSE SEXONS									
Printed Nam	ne: Chase So	ettle		Approved by District Supervisor Environmental Specialist									
Title: NM E	nvironment	al Regulatory		Approval Da	nte: 3/26/14	E	xpiration	Date: 5	27/1	4			
E-mail Add	ress: csettle	@yatespetrole		Conditions of Approval: SNBMIT FINAL Attached FT									
Date: Wedn				2RP- C-141 BY 5/27/14 1RP-05-14-3035									
* Attach Add	litional She	ets If Neces	sarv							•			