District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Revised August 8, 2011
Submit 1 Copy to appropriate District Office in

Form C-141

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action												
nHMPI	41213	5045			OPERATOR /			Initial Report Final Report				
Name of Company LRE Operating, LLC 28/994						Contact Michael Barrett						
			ouston, TX 7700	2	Telephone No. 575-623-8424							
Facility Name Staley State Battery (Well #1) Facility Type Production & Storage												
Surface Ow	ner C.O.C	j.	Mineral O	wner	State API No. 30-015-32-184							
LOCATION OF RELEASE 3/28 4												
						th/South Line Feet from the		East/West Line East		County Eddy		
Latitude 32.637158 Longitude 104.077749												
NATURE OF RELEASE												
										Volume Recovered 7 Oil & 1 Wtr		
		er Treater Gas			Date and Hour of Occurrence Date				e and Hour of Discovery			
Week C' 0						4/5/14 pm 4/5/14 @ 8:45 pm						
Was Immediate Notice Given?  ☐ Yes ☐ No ☒ Not Required If YES, To Whom?												
By Whom? N/A						Date and Hour N/A						
Was a Watercourse Reached?  ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.						
If a Watercourse was Impacted, Describe Fully.*												
N/A												
Describe Cause of Problem and Remedial Action Taken.*  RECEIVED												
· ·										1		
Picked up standing fluid.												
Replaced gas		****		NMOCE				D ARTES'				
Describe Area Affected and Cleanup Action Taken.*												
		ly in bermed a			ound fl	ow lines and e	equipment.					
Hand dug and hydro vac was used to remove contaminated soil around flow lines and equipment.  Area that was covered by spray was treated 3 times with micro-blaze.												
I haraby cont	ify that the	nformation a	van ahav	is true and compl	oto to t	the best of my	knowledge and u	un dansta	nd that num	guant to NMOCI	) rules and	
				nd/or file certain re								
				ce of a C-141 repor								
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other												
		ws and/or regi		nance of a C-1411	<del></del>		<u> </u>			·		
Signature: Muli A A S  Printed Name: Michael Barrett						OIL CONSERVATION DIVISION						
						Approved by Environmental Specialist:						
Title: Produc	tion Superv	isor			Approval Date: 5/1/14 Expiration Date: NA							
E-mail Addre	ess: mbarret	t@limerockre	om		Conditions o	f Approval:			Attached	1		
Date: 04/14	/14		75-623-8424	•	Kelliediation per OCD Rule & — —							
Attach Addi				J-023-0727	_ (	Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:  2PP-2274						
			•				TEN LAICK	I DAN:		CFT-	17	

## Patterson, Heather, EMNRD

To:

mbarrett@limerockresources.com

Cc:

Bratcher, Mike, EMNRD

Subject:

Staley State Battery (Well #1)

Mr. Barrett,

Your final report C-141 for the Staley State Battery cannot be approved at this time due to incomplete reporting. We will need a site map and analytical data showing that this site has been cleaned up to meet NMOCD standards before we can close this report.

Thank you,

Heather Patterson Environmental Specialist NMOCD District II (575)748-1283 ext.101