

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

MAY 14 2014

Form C-141  
Revised August 8, 2011

NMOC DARTESIA  
Submit a copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NMCB1413536397

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Pyote Water Solutions, LLC	Contact	Jerry Burton
Address	400 W Illinois Ave Ste 950	Telephone No.	432-448-4917
Facility Name	Willow Lake Swd	Facility Type	Disposal
Surface Owner	Pyote Water Solutions, LLC	Mineral Owner	Pyote Water Solutions, LLC
		API No.	30-015-21499



LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	22	24s	28E	200 ft	south	NO	NO	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release	production water	Volume of Release	800-1000 bbl	Volume Recovered	0	
Source of Release	Franco's driver hit cement barrier, ran over load line 1 & 2		Date and Hour of Occurrence	4/25/14	Date and Hour of Discovery	4/25/14 14:25 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required		If YES, To Whom?	Jerry Burton		
By Whom?	anonymous driver reported it		Date and Hour	4/25/14 15:75 hrs		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*	NONE					
Describe Cause of Problem and Remedial Action Taken.* driver from Franco's Trucking hit a cement barrier into load line 1 & 2, busted underground lines. Driver got off looked at accident he made and left. Did not report accident to Jerry or his work. Occurred around 2:30 am. Anonymous driver called Jerry at 3:45 to report mess and water all over at Willow Lake. Called OCD 4-25-14. Notified land owner as well, Scott Branson. After reviewing video, Franco's was notified as well.						
Describe Area Affected and Cleanup Action Taken.* Scott Branson land owner will not let us clean up the land, due to he wants damages cost. And he will have his own company due the cleanup. Undecided from SB & Franco's Trucking cost of damages.						
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.						

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jerry Burton	Signed By:  Approved by Environmental Specialist:	
Title: Pyote Water Solutions NM Superintendent	Approval Date: 5/15/14	Expiration Date: NA
E-mail Address: jerry@pyotewatersystems.com	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 6/15/14	Attached <input type="checkbox"/>
Date: 4-30-12	Phone: 432-448-4917	

\* Attach Additional Sheets If Necessary

2RP-2305