BECEIVED

District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 State of New Mexico
Energy Minerals and Natural Resources

QOO SHOHOil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action **OPERATOR** Initial Report Final Report **Contact:** Bradley Blevins Name of Company: Chevron Address: 1616 West Bender **Telephone No.:** (575) 391 – 1462 ext 86424 Facility Name: Mittie Weatherly #2 Facility Type: flowline Surface Owner: Chevron USA **Mineral Owner:** API: 30-025-06648 LOCATION OF RELEASE Township Unit Letter Feet from the North/South Line Section Range Feet from the East/West Line County 1980 21S North West Lea Latitude: N 32° 28′ 52.42″ Longitude: W 103° 11′ 24.46″ NATURE OF RELEASE Type of Release: produced water Volume of Release: 242 bbls Volume Recovered: 220 bbls Source of Release: flowline Date and Hour of Occurrence: Date and Hour of Discovery: 5/7/14 5/8/14 Was Immediate Notice Given? If YES, To Whom? Geoff Leking By Whom? Bradley Blevins Date and Hour: 5/8/14 @ 06:58 Was a Watercourse Reached? If YES, Volume Impacting the Watercourse: ☐ Yes ⊠ No Not Applicable Depth to Water. ~80 ft bgs Dept & Pogrand 450 75-100' If a Watercourse was Impacted, Describe Fully.* Not Applicable Describe Cause of Problem and Remedial Action Taken.* Approximately 242 bbls of produced water were released when a flowline developed a hole. Vacuum trucks were dispatched to pick up any free standing liquids. There were approximately 220 bbls recovered. An Emergency Response Team arrived at the release area and began continuous abatement of the impacted area. Visibly stained soil was excavated and hauled away for disposal at a state approved facility. Describe Area Affected and Cleanup Action Taken.* Approximately 4,800 square feet of surface area was impacted by the release. Soil samples will be collected from release area and submitted to Cardinal Laboratories for testing. Upon receipt of laboratory analytical data from soil samples collected during delineation operations, EPI will prepare and present a Remediation Proposal for NMOCD approval. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Dradles Da Signature: Approved by District Supervisor: Printed Name: Bradley Blevins Environmental Specialist Approval Date: Title: HE Specialist Expiration Date: 07-21-19 5-20-14 Conditions of Approval: 5,72 Samples E-mail Address: bradley.blevins@chevron.com Attached [required. Delinist and remedrate Date: 5-20 - 14 Phone: (575) 391-1462 ext 86424 1RP 05-14-3039 as per NAOCO regs. Submit fixe) * Attach Additional Sheets If Necessary

C-141 by 07-21-19.

09 4323

n7014140 91020