

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	CJ Summers
Address	1017 W. Stanolind Rd, Hobbs, NM	Telephone No.	(575) 397-8216
Facility Name	Sand Dunes 34 Federal #2	Facility Type	Battery

Surface Owner	BLM	Mineral Owner		Lease No.	NM 43744
---------------	-----	---------------	--	-----------	----------

LOCATION OF RELEASE


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	34	23S	31E					Eddy

Latitude N 32.26192° Longitude W 103.75925°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	20 bbls	Volume Recovered	0 bbls
Source of Release	Power failure at the transfer pump caused frac tank overflow	Date and Hour of Occurrence	03/25/2013	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jennifer Van Curen, James Amos-BLM and Mike Bratcher-OCD		
By Whom?	Chancey Summers	Date and Hour	03/25/2013 @ 10:18 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Power failure at the transfer pump caused the frac tank to overflow and spill 20 bbls of produced water onto the ground. No fluids were recovered and power to the transfer pump was restored.

Describe Area Affected and Cleanup Action Taken.*

Power failure at the transfer pump caused the frac tank to overflow and spill 20 bbls of produced water onto the ground. No fluids were recovered and power to the transfer pump was restored. Remediation was completed in accordance with a remediation plan approved by Mike Bratcher of NMOC D via email on 10/04/2013 and approved by Jennifer Van Curen of the BLM via email on 01/07/2014.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:				OIL CONSERVATION DIVISION			
Printed Name:	Chancey Summers			Approved by District Supervisor:			
Title:	HES Specialist			Approval Date:	5/20/14	Expiration Date:	NA
E-mail Address:	Chancey.Summers@oxy.com			Conditions of Approval:	Final		Attached <input type="checkbox"/>
Date:	2-4-14			Phone:	(575) 397-8216		

* Attach Additional Sheets If Necessary

2EP-1610