

SITE INFORMATION

Report Type: Work Plan

General Site Information:

Site:	West Brushy 27 Federal #1	
Company:	COG Operating LLC - EOG Resources, Inc.	
Section, Township and Range	Section 11 T-25S R-29E	
Lease Number:		
County:	Eddy County	
GPS:	32.102081° N	103.979668° W
Surface Owner:	Federal	
Mineral Owner:		
Directions:	From the post office in Malaga, NM, travel south on Hwy 285 3.8 miles, turn left on Whitehotn Road and travel 4.0 miles, turn left and travel 1.8 miles, at caliche pit on right turn left and travel 1.5 miles to location.	

Release Data:

Date Released:	11/30/2010
Type Release:	Produced Water
Source of Contamination:	Flowline failure
Fluid Released:	80 bbls
Fluids Recovered:	0 bbls

Official Communication:


Name:	Robert McNeill	Ike Tavaréz
Company:	COG Operating	Tetra Tech
Address:	One Concho Center	400 N. Big Spring
P.O. Box	600 W. Illinois	Suite 401
City:	Midland, Texas, 79701	Midland, Texas
Phone number:	432-686-3023	432-6284559
Fax:	432-684-7137	
Email:	rmcneill@concho.com	ike.tavaréz@tetratech.com


Ranking Criteria

Depth to Groundwater:	Ranking Score	Site Data
<50 ft	20	
50-99 ft	10	
>100 ft	0	
Wellhead Protection:	Ranking Score	Site Data
Water Source <1,000 ft., Private <200 ft.	20	
Water Source >1,000 ft., Private >200 ft.	0	0
Surface Body of Water:	Ranking Score	Site Data
<200 ft.	20	
200 ft - 1,000 ft.	10	
>1,000 ft.	0	0
Total Ranking Score:	0	

Acceptable Soil RRAL (mg/kg)

Benzene	Total BTEX	TPH
10	50	5,000





EXPLANATION

- ★ RELEASE POINT
- SOIL SAMPLE LOCATIONS
- SOIL BORE SAMPLE LOCATIONS(AUDER)
- BORE HOLE SAMPLE LOCATIONS(MECHAMICAL)
- ROAD SAMPLE
- EOG FLOW LINE
- EOG FLOW LINE
- SPILL AREA



CONCHO

Figure 4

West Bushy Z7 Federal # 1

Soil Assessment
Aerial Mapping Map

Eddy County, New Mexico

Project 114440718

Date: 10/20/11

File: 114440718

feet

0 25 50

1 in = 50 feet



