


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011

**Release Notification and Corrective Action**

*nHMP14145023493*

<b>OPERATOR</b>		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company <b>Devon Energy</b>	<i>4137</i>	Contact <b>Rudy Zuniga</b>	
Address <b>PO Box 250 Artesia, NM 88211</b>		Telephone No. <b>575-390-5475</b>	
Facility Name <b>Arenoso 22 Federal 2</b>		Facility Type <b>Gas</b>	
Surface Owner <b>Federal</b>		Mineral Owner <b>Federal</b>	API No. <b>30-015-35631</b>

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	22	19S	31E	1980	South	990	East	Eddy

Latitude: 32.6440262

Longitude: -103.8512475

**NATURE OF RELEASE**

Type of Release <b>Spill Oil &amp; Produced Water</b>	Volume of Release <b>129BBLS</b>	Volume Recovered <b>128BBLS</b>
Source of Release <b>blown up water tank</b>	Date and Hour of Occurrence <b>5.24.14 12:00 PM</b>	Date and Hour of Discovery <b>5.24.14 12:00 PM</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Jeff Robertson/ BLM &amp; Mike Bratcher/ OCD</b>	
By Whom? <b>Production Foreman: Rudy Zuniga</b>	Date and Hour <b>5.24.2014 5:00 PM &amp; 5:30 PM</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <b>N/A</b>	
If a Watercourse was Impacted, Describe Fully.* <b>N/A</b>		
Describe Cause of Problem and Remedial Action Taken.* <b>Increased pressure in the water tank caused the tank to blow up. Tank will be replaced.</b>		
Describe Area Affected and Cleanup Action Taken.* <b>All but approximately 1BBL of spilled fluids was captured in lined containment around the tanks and recovered by vacuum truck on May 24, 2014. The 1BBL not recovered was lost as a result of overspray onto the caliche on the well pad. The overspray affected approximately 20'x20'. The affected caliche will be removed.</b>		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Sandra Farley</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Sandra Farley</b>	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: <b>Field Admin Support</b>	Approval Date: <i>5/30/14</i>	Expiration Date: <i>NA</i>
E-mail Address: <b>Sandy.Farley@dmv.com</b>	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. <b>SUBMIT REMEDIATION</b>	Attached <input type="checkbox"/>
Date: <b>May 27, 2014</b>	Phone: <b>575.746.5587</b>	

\* Attach Additional Sheets If Necessary

**PROPOSAL NO LATER THAN:**

*6/30/14*

*28P-2321*

**Bratcher, Mike, EMNRD**

---

**From:** Farley, Sandy <Sandy.Farley@devon.com>  
**Sent:** Tuesday, May 27, 2014 4:16 PM  
**To:** Bratcher, Mike, EMNRD; Jeff Robertson (jrobertson@blm.gov)  
**Cc:** Zuniga, Rudy; Armer, Steve; Gladden, Randy  
**Subject:** Oil & PW spill Arenoso 22 Federal 2 May 24, 2014  
**Attachments:** Arenoso 22 Fed 2 Initial C141.doc; Arenoso 22-2 Oil & PW spill & prop dmg 5.24.14 1 of3 (1).jpg; Arenoso 22-2 Oil & PW spill & prop dmg 5.24.14 1 of3 (2).jpg; Arenoso 22-2 Oil & PW spill & prop dmg 5.24.14 1 of3 (3).jpg

Good afternoon,

Attached is the initial C141 and photos for the oil & produced water spill that occurred at the Arenoso 22 Federal 2 on May 24, 2014. The hard copies will go out with tomorrow's mail.

Have a pleasant evening

*Sandra Farley*

**Field Admin Support  
Production**


**Devon Energy Corporation**  
**Artesia, New Mexico**  
**6488 Seven Rivers Highway**  
**Sandy.Farley@devon.com**  
**575 716 5587 (office)**

  
**devon**

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.

Devon Hecox 22 Feb 2 015-35631 Joe Spauld

Devon Hecox





Devon Photo

BoR. 5/24/14

015-35651

Devon Photos 10/24/12





ASUM AGENOS 21 Feb 1 015-35631

802 5/24/14

