

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: BOPCO, L.P.	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU-129 (2RP-2128)	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-29552	

LOCATION OF RELEASE

Unit Letter H	Section 20	Township 24S	Range 31E	Feet from the 1980	North/South Line South	Feet from the 660	East/West Line East	County: Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	-----------------

Latitude N 32.204440 Longitude W 103.793891

NATURE OF RELEASE

Type of Release: Crude oil and produced Water	Volume of Release: 2 bbls crude oil and 38 bbls produced water 40 bbls total fluid	Volume Recovered: 1 bbl crude oil and 29 bbls produced water. 30 bbls total fluid
Source of Release: 2 7/8" flow line	Date and Hour of Occurrence: 12/16/13 time unknown	Date and Hour of Discovery: 12/16/13 at 5:00 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency #104 and the BLM	
By Whom? Tony Savoie	Date and Hour: 12/22/13 at 3:42 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RECEIVED

MAY 20 2014

NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The flow line developed a leak at a collar connection. The well was shut in, a vacuum truck was used to pull the fluid out of the line and pick up the free standing fluid. The section of pipe was scheduled to be replaced on 12/17/13.

Describe Area Affected and Cleanup Action Taken.*

The spill impacted approximately 1,950 square feet of pasture, a crew was dispatched to the site to gather information for one-call clearance and BLM arch. Clearance. A crew started removing the heavily saturated soil at 9a.m. 12/18/13 after receiving permission from the BLM to access the site. The spill will be cleaned up in accordance to the NMOCD and BLM guidelines for spill remediation.

Approximately 1,460 cu. yds of impacted soil was excavated from an area measuring approximately 14' to 40' in width, 120' in length, and 1' to 14' in depth. Impacted soil was hauled to an NMOCD-approved disposal facility. **Please reference the attached Remediation Summary and Site Closure Request for detail of Remediation Activities.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Tony Savoie	Approval Date: 5/27/14	Expiration Date: NA
Title: Waste Management and Remediation Specialist	Conditions of Approval: Final	Attached <input type="checkbox"/>
E-mail Address: tasavoic@basspet.com		
Date: 5/20/14	Phone: 432-556-8730	

Attach Additional Sheets If Necessary