

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company COG Operating LLC	Contact Robert McNeill
Address 600 W. Illinois, Midland, Texas 79701	Telephone No. (432) 685-4332
Facility Name SRO 102 SWD	Facility Type Tank Battery

Surface Owner: State	Mineral Owner	Lease No. (API#) 30-015-21398
----------------------	---------------	-------------------------------

LOCATION OF RELEASE

Unit Letter G	Section 16	Township 26S	Range 28E	Feet from the	North/South Line	Feet from the	East/West Line	County
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	--------

Latitude N 32.14430° Longitude W 104.09031°

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release 20 bbls	Volume Recovered 15 bbls
Source of Release: Durco pump discharge 3X2 swage	Date and Hour of Occurrence 2/21/2013	Date and Hour of Discovery 2/21/2013 5:30 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A

RECEIVED

MAR 05 2014

NMOCD ARTESIA


Describe Cause of Problem and Remedial Action Taken.*

A Durco pump discharge 3X2 swage cracked when the pump kicked on. Replaced with new plastic coated parts

Describe Area Affected and Cleanup Action Taken.*

Initially 20 bbls of produced fluid were released into the lined facility. 15 bbls were recovered with a vacuum truck. The majority of the spill remained inside the facility. The contaminated gravel was removed from the facility and replaced with new gravel. Tetra Tech inspected site and collected samples to define spills extent outside of the firewall. Soil that exceeded RRAL was removed and hauled away for proper disposal. Site was then brought up to surface grade with clean backfill material. Tetra Tech prepared closure report and submitted to NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Ike Tavarez	Approved by District Supervisor:		
Title: Project Manager	Approval Date:	Expiration Date:	
E-mail Address: Ike.Tavarez@TetraTech.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 11-14-13	Phone: (432) 682-4559		

* Attach Additional Sheets If Necessary

2RP-1568