

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

2RP-1855

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BOPCO, L.P.	Contact: Jody Walters	
Address: 522 W. Mermod, Suite 704 Carlsbad, NM 88260	Telephone No. 575-887-7329	
Facility Name: PLU Big Sinks 14-25-30 USA Battery #001H	Facility Type: Exploration and Production	
Surface Owner Federal	Mineral Owner Federal	API No. 30-015-39508

LOCATION OF RELEASE


Unit Letter N	Section 14	Township 25S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	-------------

Latitude N32.124358 Longitude W130.853639

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 42 bbls	Volume Recovered: 38 bbls
Source of Release Open valve on tank	Date and Hour of Occurrence 8/1/2013 time is unknown	Date and Hour of Discovery 8/12/013 4:20PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD Artesia Office	
By Whom?	Date and Hour 01-22-13 2:20 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
NA



Describe Cause of Problem and Remedial Action Taken.*
The ZH Services Inc. vacuum truck operator was pulling a load of produced water from the water tanks. He had pulled water level down below load line and disconnected the hose leaving the location. He had forgotten to close the valve on the tank about 1.5 hours later another truck arrived on location to haul another load of produced water. This driver closed the leaking valve and recovered the free standing fluid.

Describe Area Affected and Cleanup Action Taken.*
Spill affected approximately 7400 sq. ft. of the tank battery. The spill was delineated by Diversified Field Services, Inc. Impacted soils were removed to a NMOCD approved disposal facility. Confirmation samples were then submitted to a commercial lab for analyses. Backfill of the excavation was approved by the NMOCD. The excavation was backfilled and bladed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Waste Management and Remediation Specialist		Approval Date: 5/15/14	Expiration Date: NA
E-mail Address: tasavoie@basspet.com		Conditions of Approval: Final	
Date: 3/12/14 Phone: 432-556-8730		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-1855