District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD State of New Mexico Energy Minerals and Natural Resources

Revised August 8, 2011

Form C-141

JUL 0 3 2013 Conservation Division 1220 South St. Francis Dr.

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED Santa Fe, NM 87505

			Rele	ease Notific	catio	n and Co	rrective A	ctior	1			
					OPERAT		al Report		Final Repor			
Name of Co					Contact Xavier Martinez							
Address P			1		Telephone No. (432) 208-3319							
Facility Nar	ne Bunin	#006			Facility Type Well Location							
Surface Ow	ner Buni	in, N B Prop	Mineral C	Owner	API No. 30-025-39547							
				LOCA	ATIO	N OF REI	LEASE					
Unit Letter	Section	Township	Range	Feet from the	_	/South Line	Feet from the	East/\	Vest Line	County		
Α	13	218	37E	351		FNL	980	FEL		Lea		
			La	fifude	•	Longitud	e			-		
			2511			-						
Type of Relea	asa Oil an	d Droduced w	NAT	UKE	E OF RELEASE Volume of Release 20 bbls Volume Recovered 10 bbls							
Source of Re									Hour of Discovery			
					unknown 7/2/13 9:45 am							
Was Immedia	ate Notice C		٧., ٢	No Not Re		If YES, To Whom?						
	•		I NO I NOI RO	equirea	d Geoff Leking – Jeffery Robertson –							
By Whom? I	RECS				Date and Hour 7/2/13 NMOCD 3:45 pm							
Was a Watero	nurse Read	hed?			BLM 3:48 pm If YES, Volume Impacting the Watercourse.							
mas a materi	course reac		No									
If a Watercou	rse was Im	pacted, Descri	be Fully.*									
	•	,	•				. *	~	J=691			
Describe Cau	se of Proble	em and Remed	lial Action	Taken.*				<u> </u>	3-61			
Describe Cause of Problem and Remedial Action Taken,* The stuffing box released 20 bbls of oil and produced water. A vacuum truck was called on site and retrieved 10 bbls of oil and produced water. The												
affected pad v	was covered	l over with ca	liche to pr	otect wildlife unti	il the on	e-call clears.	The site will be d	elineate	ed to detern	nine further	actions.	
Describe Area	a Affected a	und Cleanup A	ction Tak	en.*								
		•		•								
•												
							knowledge and und d perform correct					
							irked as "Final Re					
should their o	perations h	ave failed to a	dequately	investigate and re	emediat	e contamination	on that pose a thre	eat to gr	round water	r, surface wa	iter, hun	nan health
or the environ federal, state,				tance of a C-141	report d	loes not relieve	the operator of r	esponsi	ibility for co	ompliance w	ith any	other
rederm, state,	1/		,				OIL CONS	SERV	ATION	DIVISIO	N.	
Kowa WIII												
Signature:	/ Cer	11/0	 		Approved by Environmental Specialist							
Printed Name	: Xavier M	1artinez				Approved by I	Environmentati S	echilis Tuyin		Specialis	<u>st</u> (J
Title: EH&S	Technician	1			Approval Date	: 7/8/13			Date: 9 9			
					1		•	-			, _	
E-mail Addres	ss: Xavier.	.martinez@ap	com		Conditions of Approval: SUBMIT FIMAL C-141 BY 919113			Attached				
Date: 7/	2/201	3	(432) 208-331	9				IRF-9-13-2946				
Attach Additi	ional Shee	ts If Necessa		(, 200 001	L,	······································				1 4 4 4		· · ·