State of New Mexico Energy Minerals and Natural Resources

> **Oil Conservation Division** 1220 South St. Francis Dr.

R	E	C	Ε	1	V	E	D	

JUN 06 2014

Form C-141 Revised August 8, 2011

Submit I Copy to appropriate District Office in NMOCD An accordance with 19.15.29 NMAC.

1220 S. St. Fra	ncis Dr., Sant	a Fe, NM 8750	5	S	anta F	e, NM 875	505					
	and a second		Rel	ease Notifi	catio	n and Co	orrective A	ction	AND A REAL PROPERTY AND A REAL PROPERTY.			
nHMPI	Ý163	48097		<i>i</i> .		<b>OPERA</b>	TOR		X Initi	al Report		Final Report
Name of Co	ompany: C	IMAREX E	NERGY	16268	3	Contact: Jan						
				and TX 79701			No. (575) 706-0					
	•	id 3 federal	l	· · · · · · · · · · · · · · · · · · ·		Facility Typ	be: Battery-Oil	well				
Surface Owner Mineral Owner								API No	, 30-015-3	8979		
				LOC	ATIO	N OF RE	LEASE					
Unit Letter Section Township Range Feet from the North/South Line Feet							Feet from the	East/We	est Line	County		
$\mathbb{D}$	3	19-S	30-E							Eddy		
L	- <u>L</u>	I	L	I	<u> </u>	· · · · ·				L		<u>.</u>
				Latitude 32.	.695989	) _ Longitud	le -103.965168					
				NAT	<b>FURE</b>	OF REL	EASE					
Type of Rele							Release 4 Oil /9			Recovered		
Source of Re	lease Stuff	ing box packi	ng			Date and Hour of OccurrenceDate and Hour of Discovery6/6/2/14 @7:00 am@ 12:00pm					y 6/2/2014	
Was Immedi	ate Notice (					If YES, To	Whom? Mike B		MOCD(I			
Required		XĮ	_ Yes	🗌 No 🗌 Not		Jennifer Va	an Curran BLN	1 (by ema	uil)			
By Whom?	lames Tinn	ev				Date and Hour 6/2/14 @ 1:00 pm						
Was a Water						If YES, Volume Impacting the Watercourse.						
			Yes x	No								
If a Watercou	urse was Im	pacted, Descr	ibe Fully. <sup>3</sup>	*		<b>E</b>						
			•									
							•					
stuffing box		em and Reme ked	dial Action	n Taken.*				Ň			·	
										ι.		
		and Cleanup A										
				'– 2" deep. Repa	ired stut	fing box. Pick	ked up standing fl	uid and sc	rapped a	rea with bac	k hoe t	o pick up
contaminated	i son. Taioi	n to sample af	lected area	a.								
I hereby certi	fy that the i	nformation gi	ven above	is true and comp	lete to th	he best of my	knowledge and w	nderstand	that purs	uant to NM	OCD n	ules and
regulations al	l operators	are required to	o report an	nd/or file certain r	elease n	otifications an	d perform correc	tive actior	ns for rele	ases which	may en	danger
public health	or the envir	onment. The	acceptanc	e of a C-141 repo	ort by the	e NMOCD ma	arked as "Final Re	eport" doe	s not relie	eve the oper	ator of	liability
or the enviror	ment. In a	ddition, NMO	CD accep	tance of a C-141	report de	bes not relieve	the operator of r	esponsibil	lity for co	, surface wa mpliance w	ith anv	other
federal, state,	or local lav	vs and/or regu	lations.									
							OIL CONS	SERVA	TION	DIVISIC	N	
Signature: 9	rmes Tinney								/	/		
D	•		<u> </u>			Approved by I	Environmental Sp	pecialist:	K	. / /	/	
Printed Name	Printed Name: James Tinney						·····		11-	cre	m	
Title: Production Foreman						Approval Date	: le /12/11,		piration <b>E</b>	Date:	VA	
E mail A 11												
E-mail Addre	ss: jtinney@	vcimarex.com			— I <b>(</b>	Conditions of emediation	Approval: per OCD Rule &	Guideline	es, <b>&amp;</b>	Attached		
Date: 6/6/201				5) 706-0095	lik	e approval b	y BLM. <u>SUBMIT</u>	REMEDIA	TION			
Attach Addit	ional Shee	ts If Necessa	ry			PROPC	SAL NOLATER	<u>THAN:</u>			P-	2340
							110119	1		4	•	10

7/12

## Bratcher, Mike, EMNRD

From: Sent: To: Cc: Subject: Attachments: James Tinney <ltinney@cimarex.com> Friday, June 06, 2014 12:16 PM Van Curen, Jennifer Bratcher, Mike, EMNRD; Johnny Titsworth; Mark Martino Intrepid 3 fed 1 C-141 Intrepid 3-1 stuffing box release.doc

James Tinney Production Foreman Hobbs West <u>575-706-0095 cell</u> 575-628-3447 office 575-628-3566 fax

*CIMAREX* jtinney@cimarex.com