District 1 1925 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aziec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

Attach Additional Sheets If Necessary

State of New Mexico Energy Minerals and Natural Resource

MAY 15 2014

RECEIVE

Form C-141 Revised August 8, 2011

ZRP-2341

NMOOD ARTEMA priate District Office in with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505

Release Notification and Corrective Action **OPERATOR** ☐ Initial Report Final Report Occidental Permian Contact Charles F. Bullard Jr. 157984 6 Desta Drive, Ste. 6000, Midland, TX 79705 Address Telephone No. (432) 685-5719. Facility Name Federal 12 #2H Facility Type Drilling location Surface Owner BLM Mineral Owner API No. 30-015-41344 LOCATION OF RELEASE Unit Letter Range North/South Line Section Township Feet from the Feet from the Hast/West Line 238 30E 1159 South 1543 0 Past Eddy County, NM Latitude N 32.32984° Longitude W 103.83012° NATURE OF RELEASE 20 bbls Type of Release Produced water Volume of Release 45 bbls Volume Recovered Transfer from cellar to open-top tank and valve was Date and Hour of Occurrence Source of Release Date and Hour of Discovery left open causing water spill over 03/18/2014 Was Immediate Notice Given? If YES, To Whom? ☐ Yes ☒ No ☐ Not Required Bebby Girndt, BLM By Whom? Tommy Sikes Date and Hour 03/18/2014 at 6:30 am Was a Watercourse Reached? If YES, Volume Impacting the Watercourse, ☐ Yes ☐ No If a Watercourse was Impacted, Describe Fully,* Describe Cause of Problem and Remedial Action Taken.* A transfer from cellar to open-top tank and the valve was left open gausing 45 bbis of produced water to leak onto the ground. A vacuum truck recovered 20 bbls of produced water and the transfer/valve were closed. Describe Area Affected and Cleanup Action Taken.* The affected area is approximately 40° x 45° around the outside of the sub and along the pipe wrangler. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM i hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Approved by Environmental Specialist: Printed Name: Charles F. Bullard Jr. Title: Drilling HES Ops Advisor Approval Date: Expiration Date: E-mail Address: Charles Bullard@oxy.com Conditions of Approval: Attached [Kemediation per OCD Rule & Guidelines, & (432) 894-3769 Phone.

like approval by BLM. SUBMIT REMEDIATION

PROPOSAL NO LATER THAN:

Bratcher, Mike, EMNRD

From:

Kathy Purvis <kathy@bbcinternational.com>

Sent:

Thursday, May 15, 2014 11:44 AM

To:

Bratcher, Mike, EMNRD; jvancure@blm.gov

Cc:

Charles_Bullard@oxy.com; cbrunson@bbcinternational.com;

kswinney@bbcinternational.com; jgilkey@bbcinternational.com

Subject:

Federal 12 #2H

Attachments:

Initial C-141, Federal 12 #2H.pdf

Attached is the initial C-141 for a leak that occurred at the Federal 12 #2H on 03/18/2014 in Eddy County, NM. Receipt notification via email is greatly appreciated.

Kathy Purvis

BBC International, Inc.

1324 W. Marland

Hobbs, NM 88240 Phone: (575) 397-6388

Fax: (575) 397-0397 Email: <u>kathy@bbcinternational.com</u>