District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division

1220 South St. Francis Dr.

Santa Fr. NIM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141 Revised August 8, 2011

Santa Fe, NM 87505

			Kele	ease Nothic	ation	i and Co	rrective A	ction					
						OPERATOR   Initial				al Report		Final Report	
Name of Company Apache Corporation						Contact Natalie Gladden							
Address PC				Telephone No. 575-390-4186									
Facility Name NEDU #718						Facility Type Production Well							
Surface Owner Deck Estate Mineral Owner						State of NM API No. 30-025-34742							
				LOCA	TION	OF REI	LEASE						
Unit Letter	Section	Township	Range	Feet from the	North/	South Line	Feet from the	East/V	Vest Line	County			
n	15	210	225	14	FSL		1098	FEL		Lea			
Р	13	21S .	37E	14	LOL		1098	1 1 2 2		Lea			
	LatitudeLongitude												
	NATURE OF RELEASE												
Type of Rele					Volume Recovered 12								
Source of Release Back pressure valve										Pate and Hour of Discovery 8/19/2011			
Was Immediate Notice Given?  ☐ Yes ☐ No ☐ Not Required						If YES, To Whom? Geoffrey Leking				HOBBS OCD			
By Whom? Natalie Gladden						Date and Hour 08/19/11 11:30am by email							
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse. FEB 1 3 2012							
If a Watercourse was Impacted, Describe Fully.*												)	
DTW = 49													
Describe Cause of Problem and Remedial Action Taken.*  Back pressure plugged up and blew out releasing 15bbls of oil and recovering 12bbls of oil. Vacuum truck was called out to pick-up standing fluid. Site was back-dragged until one-call was cleared, to keep the cattle away.  Describe Area Affected and Cleanup Action Taken.*													
Describe Area Affected and Cleanup Action Taken.*  Site will be excavated and remediated to meet NMOCD Guidelines for Spills and Releases.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
regulations al public health should their or or the environ	Il operators for the environment. In a	are required to comment. The ave failed to a	report ar acceptance dequately CD accep	nd/or file certain rece of a C-141 repoint investigate and retained for a C-141 repoint ance of a C-141 repoint and a C-141 repoint a C-14	elease no rt by the emediate	otifications are NMOCD m contaminati	nd perform correct arked as "Final Ro on that pose a thre	tive acti eport" d eat to gr	ons for rel oes not rel ound water	eases which i ieve the opera r, surface wat	may end ator of l er, hum	danger liability nan health	
Signature: Natalie Gladden  Printed Name: Natalie Gladden							OIL CONSERVATION DIVISION  Approved by Environmental Specialist  Environmental Specialist						
						Approval Date: 08   19   11   Expiration Date: 10   19   11							
						Conditions of Approval: SVBMIT FIMAL C-141 BY 10/19/11			Attached []				
Attach Addi	tional Char	to If Nagage	7.57	-									

\* Attach Additional Sheets If Necessary

JUN \$ 8 2014 NJAD1416 852101

L.