

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

Initial Report  Final Report

Name of Company: BOPCO, L.P.	Contact: Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, NM 88220	Telephone No. 432-556-8730
Facility Name: Poker Lake Unit Well #123	Facility Type E&P
Surface Owner Federal	Mineral Owner Federal
API No. 30-015-28526	

#### LOCATION OF RELEASE

Unit Letter M	Section 22	Township 24S	Range 31E	Feet from the 1980	North/South Line SL	Feet from the 1980	East/West Line WL	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	------------------------	-----------------------	----------------------	----------------

Latitude 32.200969 Longitude 103.767830

#### NATURE OF RELEASE

Type of Release Produced Water and Crude Oil	Volume of Release 20 bbls PW 6 bbls oil	Volume Recovered 10 bbls total
Source of Release Well Head	Date and Hour of Occurrence 5/28/12 Time unknown	Date and Hour of Discovery 5/28/12 8:30 P.M.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency #104 and BLM Jim Amos	
By Whom? Tony Savoie	Date and Hour 05/29/12 8:17 A.M.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**RECEIVED**  
MAY 30 2014  
NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.\*  
NA

Describe Cause of Problem and Remedial Action Taken.\*  
Fluid was discovered coming from an open 1" valve on the wellhead and a broken gauge. The well was shut in and the valves closed.

Describe Area Affected and Cleanup Action Taken.\*  
Approximately 2600 sq. ft. of caliche pad and approximately 60 sq. ft. of pasture land was affected by the spill from the open valve. Approximately 4000 sq. ft. of pasture land was misted with oil and water from the broken gauge. The site was excavated and soil samples were collected from backhoe trenches. The samples were sent to a commercial lab for analyses. The excavation was installed with a 20 mil reinforced plastic liner at 3 ft. and padded with imported sand. The excavation was capped with caliche, and the site was leveled and dressed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Waste Mgmt. & Remediation Specialist	Approval Date: 6/5/14	Expiration Date: NA
E-mail Address: TASavoie@BassPet.co	Conditions of Approval: <i>Final</i>	Attached <input type="checkbox"/>
Date: 5/30/14 Phone: 432-556-8730		

\* Attach Additional Sheets If Necessary

2RP-1203