

Hobbs, NM 88240

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Avenue, Artesia, NM 88210

Brazos Road, Aztec, NM 87410

IV
S. St. Francis Dr., Santa Fe, NM 87505

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Myox 32 State #003H	Facility Type	Flowline

Surface Owner	State	Mineral Owner	Lease No. (API#) 30-015-41642
---------------	-------	---------------	-------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	32	25S	28E					Eddy

Latitude 32 05.660

Longitude 104 07.012

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 18bbls	Volume Recovered 17bbls
Source of Release Poly flowline	Date and Hour of Occurrence 01-17-2014	Date and Hour of Discovery 01-17-2014 4:20pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION
ARTESIA DISTRICT

JUN 09 2014

RECEIVED

Describe Cause of Problem and Remedial Action Taken.*

Poly crew cut into the line and squeezed off both ends. The water transfer pump kicked on building up pressure until the clamp on the upstream side failed. Shut down transfer pump and fused the line back together.

Describe Area Affected and Cleanup Action Taken.*

Initially 18bbls of produced water were released. We were able to recover 17bbls of produced water with a vacuum truck. All free fluids have been recovered. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Michelle Mullins</i>	OIL CONSERVATION DIVISION	
Printed Name: Michelle Mullins	Approved by District Supervisor: <i>[Signature]</i>	
Title: Environmental Coordinator	Approval Date: 6/6/14	Expiration Date: N/A
E-mail Address: mmullins@concho.com	Conditions of Approval: <i>Final</i>	Attached <input type="checkbox"/>
Date: 06-06-2014	Phone: 432-934-1052	

* Attach Additional Sheets If Necessary

2RP-2202