

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
20 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JUN 12 2014

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nHMP 1417630538

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Rabbit Hunter 10 State #002H	Facility Type	Tank Battery
Surface Owner	State	Mineral Owner	
		Lease No. (API#)	30-015-39038

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	10	26S	28E					Eddy

Latitude 32.05160

Longitude 104.07303

NATURE OF RELEASE

Type of Release	Volume of Release	Volume Recovered
Produced water	100bbls	
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
2" check valve	06-07-2014	06-07-2014 07:00am
Was Immediate Notice Given?	If YES, To Whom?	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	Mike Bratcher - NMOCD	
By Whom? Michelle Mullins	Date and Hour	06-09-2014 07:28am
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

2" check valve corroded on the water pump. Replaced the 2" check valve.

Describe Area Affected and Cleanup Action Taken.*

Initially 100bbls of produced water were released. We were able to recover 95bbls of produced water with a vacuum truck. The spill was contained inside the lined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned and we has replaced with fresh gravel as necessary. This location has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert Grubbs Jr.</i>		OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.		Approved by District Supervisor: <i>Hubert</i>	
Title: Senior Environmental Coordinator		Approval Date: 6/25/14	Expiration Date: NA
E-mail Address: rgrubbs@concho.com		Conditions of Approval: NA Final	Attached <input type="checkbox"/>
Date: 06-12-2014	Phone: 432-661-6601		

Attach Additional Sheets If Necessary

2RP-2353

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Thursday, June 12, 2014 2:42 PM
To: Bratcher, Mike, EMNRD
Cc: Robert McNeill; Production Mail
Subject: C-141 Initial/Final Report - 06-07-2014
Attachments: 06-07-2014 Rabbit Hunter 10 State #002H (TB) Initial - Final.pdf

Mr. Bratcher,

Please see attached the C-141 Initial/Final Report for a release that occurred at our Rabbit Hunter 10 State #002H (TB) on 06-07-2014 in Eddy County New Mexico. This is a lined facility.

Thank you,

Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com
Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701



CONFIDENTIALITY NOTICE: *The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.*

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.