

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

JUN 25 2014

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nHMP14/784/745

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 TH Street	Telephone No. 575-748-4217	
Facility Name Benson Deep AAS Federal #2H	API Number 30-015-41247	Facility Type Battery

Surface Owner Federal	Mineral Owner Federal	Lease No. NMLC028978B
--------------------------	--------------------------	--------------------------

LOCATION OF RELEASE

Unit Letter D	Section 33	Township 18S	Range 30E	Feet from the 660	North/South Line North	Feet from the 300	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.70900 Longitude 103.85019



NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 19 B/O	Volume Recovered 19 B/O
Source of Release Oil tank equalizer	Date and Hour of Occurrence 6/13/2014; AM	Date and Hour of Discovery 6/13/2014; AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		

Describe Cause of Problem and Remedial Action Taken.*
Oil tank overflowed; equalizers were closed. Vacuum truck(s) called.

Describe Area Affected and Cleanup Action Taken.*
An approximate area of 70' X 5' was affected within the lined/bermed battery. Oil tank overflowed, equalizers were opened, and vacuum trucks were called to recover the released oil (19 B/O). 100% of the crude oil was recovered using vacuum trucks. Depth to Ground Water: >100' (approximately 175', Section 33, T18S-R30E, per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 0. Based on battery being lined/bermed and all crude oil was recovered, Yates Petroleum Corporation requests closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by District Supervisor: 	
Title: NM Environmental Regulatory Supervisor	Approval Date: 6/27/14	Expiration Date: NA
E-mail Address: boba@yatespetroleum.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: Wednesday, June 25, 2014 Phone: 575-748-4217	2RP- NA - Final	

* Attach Additional Sheets If Necessary

2RP-236e1

Bratcher, Mike, EMNRD

From: Tanna Adams <TCArms@yatespetroleum.com>
Sent: Wednesday, June 25, 2014 2:47 PM
To: Bratcher, Mike, EMNRD
Cc: jamos@blm.gov; Bob Asher
Subject: Benson Deep AAS Federal #2H
Attachments: Benson Deep AAS Federal .pdf

Mr. Bratcher,

Please find attached the signed C141 Initial/Final for the below listed location:

**Benson Deep AAS Federal #2H
30-015-41247
Section 33, T18S-R30E
660' FNL & 300' FWL
Eddy County, New Mexico**

Thank you,

Tanna Adams

Yates Petroleum Corporation

Environmental Tech

Environmental Department

TCArms@yatespetroleum.com

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
