

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD

JAN 03 2013

RECEIVED

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

| | | |
|--------------------------------------|------------------------------|----------------------|
| Name of Company Apache Corporation | Contact Natalie Gladden | |
| Address PO Box 1849 Eunice, NM 88231 | Telephone No. 575-390-4186 | |
| Facility Name NEDU #220 | Facility Type Producing well | |
| Surface Owner State of NM | Mineral Owner State of NM | API No. 30-025-06358 |

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| J | 2 | 21S | 37E | 2886' | FNL | 2307' | FEL | Lea |

Latitude _____ Longitude _____

NATURE OF RELEASE

| | | |
|--|---|---------------------------------------|
| Type of Release Produced water and oil | Volume of Release 40 | Volume Recovered 30 |
| Source of Release Flowline | Date and Hour of Occurrence 12/27/2012 | Date and Hour of Discovery 12/27/2012 |
| Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? Leking | |
| By Whom? Natalie Gladden | Date and Hour 12/28/2012 642am | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |


If a Watercourse was Impacted, Describe Fully.*

DTW = 49'

Describe Cause of Problem and Remedial Action Taken.*
Flowline ruptured due to freezing weather. Standing fluid was recovered and initial assessment of the release area has been conducted.

Describe Area Affected and Cleanup Action Taken.*
The release area is in a sandy loom area. Verticals will be excavated to find depth and extent of contamination then a remediation plan will be formed and will be followed to closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|--|--|--|
| Signature:  | OIL CONSERVATION DIVISION | |
| Printed Name: Natalie Gladden |  Approved by Environmental Specialist Environmental Specialist | |
| Title: Sr. Environmental Tech | Approval Date: 1/03/13 | Expiration Date: 3/4/13 |
| E-mail Address: natalie.gladden@apachecorp.com | Conditions of Approval: SUBMIT FINAL C-141 BY: 3/4/13 | Attached <input type="checkbox"/> 1RP-9-13-2948 |
| Date: 12/28/2012 | Phone: 575-390-4186 | |

* Attach Additional Sheets If Necessary

NSA 1417750328

