

HOBBS OCD

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUN 04 2014

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company - EOG Resources, Inc.	Contact - Ryan Kainer
Address - 5509 Champions Drive, Midland, TX 79706	Telephone No. (432) 686-3662
Facility Name - Diamond 31 Fed Coin 2H (CTB)	Facility Type - Tank Battery
Surface Owner - New Mexico	Mineral Owner - New Mexico
API No. 30-025-29000	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	31	T24S	R34E	50	N	403	W	Lea

Latitude 32.1810 Longitude -103.5154

NATURE OF RELEASE

Type of Release - Produced Water	Volume of Release - 60 bbls	Volume Recovered - 50 bbls
Source of Release - Split in a poly line	Date and Hour of Occurrence: 6/4/2014, 1:00 PM	Date and Hour of Discovery 6/4/2014, 1:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffery Leking (NMOCD) Jennifer Van Curen (BLM)	
By Whom? Ryan Kainer	Date and Hour 6/4/2014, 2:30PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* NA		

Depth to g H₂O 75'-100'



Describe Cause of Problem and Remedial Action Taken.*
Approximately 60 bbls of produced water was released from a split poly line. Approximately 50 bbls of fluids were collected from the release. All release fluids occurred off location.

Describe Area Affected and Cleanup Action Taken.*

The spill area will be sampled and analyzed for Chlorides and Total Petroleum Hydrocarbons. The impacted area will be excavated, stockpiled on poly-plastic, and transported to an approved disposal facility. Clean material will be backfilled within the excavated area to normal grade.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Ryan Kainer	Approval Date: 7-2-14	Expiration Date: 9-5-14
Title: Sr. Safety & Environmental Rep.	Conditions of Approval:	
E-mail Address: ryan_kainer@eogresources.com	Attached <input type="checkbox"/>	
Date: 6/4/2014 Phone: 432-686-3662	Deliniate & remediate the site 7-14-3137	

* Attach Additional Sheets If Necessary

as per NMOCD guides
Submit final C-141 by
9-5-14

orig 7377
AT01418358353

JUL 02 2014