

JUL 03 2014

Form C-141  
Revised August 8, 2011

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

## Release Notification and Corrective Action

## OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Silver Spike Energy operating of NM	Contact	Adam Cunyus
Address	203 W. Wall St. STE 920 Midland, TX 79701	Telephone No.	432-288-3903
Facility Name	Cooper #1	Facility Type	Oil Well / Tank Battery
Surface Owner	Mineral Owner		API No. 30-025-828166

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	02	17S	38E	467	FNL	2173	FNL	Lea County

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

## NATURE OF RELEASE

Type of Release	produced water	Volume of Release	~ 15-20 bbls	Volume Recovered	all
Source of Release	Stock tanks	Date and Hour of Occurrence	6-11-14 11:00am	Date and Hour of Discovery	6-11-14 3:00pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Maxey Brown		
By Whom?	Adam Cunyus	Date and Hour	6-11-14 12:00pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Depth to g<sup>th</sup> 20 7100'

Describe Cause of Problem and Remedial Action Taken.\*


overflow on tank battery because transfer pump went down

Describe Area Affected and Cleanup Action Taken.\*

inside berm of tank battery  
hired vac truck to come out and suck up standing water

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

## OIL CONSERVATION DIVISION

Signature: 

Printed Name: Adam Cunyus

Title: managing member

E-mail Address: adam@silverspikeenergy.com

Date: 7/3/14

Phone: (432) 684-4522

Approved by Environmental Specialist:

Approval Date:

Expiration Date: 9-6-14

Conditions of Approval: Site Samples required

Attached ☐

Relocate &amp; remediate site 7-14-14

\* Attach Additional Sheets If Necessary

as per VTLs provided by NMOCD.

Submit Final C-141 by 9-6-14

og rid 300017

170 14 18434009

pro 14 18434482

JUL 03 2014

Singer

707