

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

HOBBS OCD

JUL 03 2014

RECEIVED

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

<b>Name of Company:</b> Chevron	<b>Contact:</b> Bradley Blevins
<b>Address:</b> 1616 West Bender	<b>Telephone No.:</b> (575) 391 - 1462 ext 86424
<b>Facility Name:</b> Brunson Argo SWD	<b>Facility Type:</b> tank battery

<b>Surface Owner:</b> C&V Properties, LLC	<b>Mineral Owner:</b>	<b>API:</b> 30-025-10137
---	-----------------------	--------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	9	22S	37E					Lea

**Latitude:** N 32° 24' 28.96" **Longitude:** W 103° 9' 56.48"

**NATURE OF RELEASE**

<b>Type of Release:</b> produced water	<b>Volume of Release:</b> 47 bbls	<b>Volume Recovered:</b> 40 bbls
<b>Source of Release:</b> tank battery	<b>Date and Hour of Occurrence:</b> 5/2/14 @ am	<b>Date and Hour of Discovery:</b> 5/2/14 @ am
<b>Was Immediate Notice Given?</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	<b>If YES, To Whom?</b> Geoff Leking	
<b>By Whom?</b> Bradley Blevins	<b>Date and Hour:</b> 5/2/14 @ 09:16	
<b>Was a Watercourse Reached?</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<b>If YES, Volume Impacting the Watercourse:</b> Not Applicable	

**Depth to Water.** ~80 ft bgs

**If a Watercourse was Impacted, Describe Fully.\*** Not Applicable

**Describe Cause of Problem and Remedial Action Taken.\*** Approximately 47 bbls of produced water were released when the pump equipment failed at the battery causing the tank to run over releasing 47 barrels of produced water to the secondary containment; no produced water escaped the containment. A vacuum truck was dispatched to pick up any free standing liquids. There were approximately 40 bbls recovered. An Emergency Response Team arrived at the release area and began continuous abatement of the impacted area. Visibly stained soil was excavated and hauled away for disposal at a state approved facility.

**Describe Area Affected and Cleanup Action Taken.\*** Approximately 2,300 square feet of surface area was impacted by the release. Soil samples will not be collected from release area due to finding a poly liner while removing contaminated soil. All contaminated soil will be removed and hauled for disposal. Upon NMOCD approval, EPI will backfill the tank battery.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

<b>Signature:</b> 	<b>OIL CONSERVATION DIVISION</b>	
<b>Printed Name:</b> Bradley Blevins	<b>Approved by District Supervisor:</b> 	
<b>Title:</b> HE Specialist	<b>Approval Date:</b>	<b>Expiration Date:</b> 9-10-2014
<b>E-mail Address:</b> bradley.blevins@chevron.com	<b>Conditions of Approval:</b> <i>liner battery</i>	<b>Attached</b> <input type="checkbox"/>
<b>Date:</b> 5-20-14 <b>Phone:</b> (575) 391-1462 ext 86424	<i>Remediate as per NMOCD guidelines</i>	7-14-5130

\* Attach Additional Sheets If Necessary

*Submit final by 9-10-2014*

*Copy id 241333  
1701418883 370  
PTO 1918830648*

JUL 09 2014