


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nHmp 1420232194

OPERATOR Initial Report Final Report

Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	SRO State Com #5H	Facility Type	Well

Surface Owner State	Mineral Owner	Lease No. (API#)	30-015-37425
---------------------	---------------	------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	8	26S	28E	660	South	330	West	Eddy

Latitude *32.051544* Longitude *104.11708*
NATURE OF RELEASE

Type of Release	Produced water and Condensate	Volume of Release	Unknown (bbls)	Volume Recovered	Unknown (bbls)
Source of Release	Well Control Issue	Date and Hour of Occurrence	07-01-2014 2:30 pm	Date and Hour of Discovery	07-01-2014 2:30 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Randy Dade - NMOCD		
By Whom?	Amanda Trujillo	Date and Hour	07-02-2014 09:30am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

During a routine pump change, while pulling tubing, the well kicked, and the BOP rams were unable to close around the tubing. A third party well service company addressed the issue. During the event fluid being releases was a light mist. All free standing fluids picked up and disposed of at an NMOCD approved facility.

Describe Area Affected and Cleanup Action Taken.*

Main impact area was contained to the pad. Bernms were constructed to control any runoff. All free fluids have been recovered. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by District Supervisor: <i>[Signature]</i>	
Title: Senior Environmental Coordinator	Approval Date: <i>7/21/14</i>	Expiration Date: <i>NA</i>
E-mail Address: atrujillo@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 07-10-2014 Phone: 575-748-6940	Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	

* Attach Additional Sheets If Necessary

8/21/14

2RP-2383