


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	Burnett Oil Co. <b>3080</b>	Contact	Shawna Matthews
Address	87 Square Lake Rd., Loco Hills, NM 88255	Telephone No.	(575) 219-6370
Facility Name	Jackson B 67	Facility Type	Well tester on site

Surface Owner	BLM	Mineral Owner		API No.	30-015-41968
---------------	-----	---------------	--	---------	--------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	24	17S	30E	2130	FNL	1785	FEL	Eddy

Latitude 32.821405 Longitude -103.922745

*nHMP 142023 4601*

**NATURE OF RELEASE**

Type of Release	An overspray of oil and produced water	Volume of Release	136 bbls	Volume Recovered	0 bbls
Source of Release	Well Tester	Date and Hour of Occurrence	7/5/2014 7:00 PM	Date and Hour of Discovery	7/5/2014 7:00 PM
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Kyle Norman	Date and Hour: Email BLM and NMOCD on 7/7/2014			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The well had a well tester on it. The well tester pressured up and popped off causing an over spray of oil and produced water.

Describe Area Affected and Cleanup Action Taken.\*

A total of 1,014,373 sq ft of lease pad and pasture land was affected by the release. The site will be assessed and a Corrective Action Plan will be submitted for NMOCD and BLM approval.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signatures: <i>Shawna Matthews</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Shawna Matthews	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Senior Production Technician	Approval Date: <i>7/21/14</i>	Expiration Date: <i>NA</i>
E-mail Address: smatthews@burnettoil.com	Conditions of Approval: remediation per OCD Rule & Guidelines, & like approval by BLM. <b>SUBMIT REMEDIATION PROPOSAL NO LATER THAN:</b>	Attached <input type="checkbox"/>
Date: 7-9-14 Phone: (575) 219-6370	<i>8/21/14</i>	<i>2RP-2385</i>

\* Attach Additional Sheets If Necessary

## Bratcher, Mike, EMNRD

---

**From:** Lara Weinheimer <lweinheimer@rice-ecs.com>  
**Sent:** Wednesday, July 09, 2014 10:42 AM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; James Amos  
**Cc:** 'Hack Conder'; 'Kyle Norman'; 'Laura Flores'; smatthews@burnettoil.com  
**Subject:** Initial C-141 for the Burnett Oil Jackson B 67  
**Attachments:** Initial C-141 Burnett Jackson B 67.pdf

Attached is the initial C-141 for the Burnett Oil Jackson 67. The release occurred on 7/5/14 and was an overspray of 136 bbls of oil and produced water. Once initial sampling is completed, a Corrective Action Plan will be submitted.

Thanks!

### **Lara Weinheimer**

Rice Environmental Consulting & Safety  
Project Scientist  
419 West Cain  
Hobbs, NM 88240  
(575) 441-0431



## **Patterson, Heather, EMNRD**

---

**From:** Kyle Norman <knorman@rice-ecs.com>  
**Sent:** Monday, July 07, 2014 3:14 PM  
**To:** jamos@blm.gov; Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD  
**Cc:** 'Hack Conder'; smatthews@burnettoil.com  
**Subject:** Burnett Jackson B 67

Good Afternoon

The Burnett Jackson B 67 had a well tester on it. It pressured up and popped off late Saturday night (7/5/14). It was just overspray, but it did cover a large area. We are gathering the information for the C-141. Once we have this filled out we will submit it. Let me know if you have any questions.

Thank You

Kyle Norman  
Project Lead  
419 W. Cain  
Hobbs NM 88240  
575-942-8542

